

1900 Komatsu PC35MR-2 Mini Excavator

| Basic information | | | |
|------------------------------------|-------------------|-------------------------------------|----------------|
| Model | PC35MR-2 | Serial No. | 9664 |
| Product category | Mini Excavator | Manufacturer | Komatsu |
| Year of manufacture | 1900 | Working hours | 1065 hours |
| Engine No. | | | |
| Detail Information | | | |
| Job Status | Civil Engineering | Cabin / Canopy | Canopy |
| Front Attachment | Standard | Type of Shoe | Rubber |
| Width of Track Shoe | 300 | Bucket Attachment | Standard |
| Other | EPA, Multi Lever | | |
| Appearance | | | |
| Engine Cover | Good Condition | Side Covers | Good Condition |
| Under Covers | Good Condition | Counter Weight | Scratched |
| Main Frame | Good Condition | Track Frame | Good Condition |
| Cabin | Good Condition | | |
| Interior | | | |
| Seat | Torn | Console | Good Condition |
| Operation | | | |
| Engine | Normal | Exhaust Gas Color | Normal |
| Swing | Normal | Wear: Swing Bearing | Slight |
| Traveling | Normal | Front Attachment | Normal |
| Front & Pins | | | |
| Boom | Normal | Arm | Normal |
| Wear: Boom Foot Pin | Slight | Wear: Boom / Arm Joint Pin | Slight |
| Wear: Arm Tip Pin | Slight | Wear: Other Pins | Slight |
| Wear / Deformation: Bucket | Good | Wear / Deformation: Blade | Normal |
| Undercarriage / Chassis / Tires | | | |
| Wear: Track Shoe / Rubber Shoe | Slight | Broken / Crack: Rubber Shoe (Right) | No |
| Broken / Crack: Rubber Shoe (Left) | No | Missing: Rubber Shoe Core | No |
| Wear: Upper Rollers | Slight | Wear: Lower Rollers | Slight |
| Oil Leak: Rollers | None | Broken / Missing: Rollers | None |
| Wear: Front Idler (Right) | Slight | Wear: Front Idler (Left) | Slight |
| Wear: Sprocket (Right) | Slight | Wear: Sprocket (Left) | Slight |
| Oil Leak: Travel Device | None | Oil Leak: Travel Pipes | None |
| Oil / Water / Air Leakage | | | |
| Oil Leak: Front Pipes | None | Oil Leak: Boom Cylinder | None |
| Oil Leak: Arm Cylinder | None | Oil Leak: Bucket Cylinder | None |
| Oil Leak: Swing Cylinder | None | Oil Leak: Blade Cylinder | None |
| Oil Leak: Engine | None | Oil Leak: Oil Cooler | None |
| Leak: Radiator | None | Leak: Cooling Pipes | None |
| Oil Leak: Fuel System | None | Oil Leak: Upper Structure | None |
| Oil Leak: Under Carriage | None | Oil Leak: Pilot Pipes | None |
| Oil Leak: Pilot Valve | None | Oil Leak: Pump Device | None |
| Overall Rating | | | |
| Appearance Evaluation | Fair | Rust / Corrosion | Slight |
| Overall Rating | Fair | | |