

1900 Komatsu D21A-7 Bulldozer/Tractor Shovel

Basic information			
Model	D21A-7	Serial No.	78535
Product category	Bulldozer/Tractor Shovel	Manufacturer	Komatsu
Year of manufacture	1900	Working hours	2621 hours
Engine No.			
Detail Information			
Job Status	General Contractor / Civil Engineering	Cabin / Canopy	Canopy
Power Transmission System	Torque Converter	Type of Shoe	Grouser
Width of Track Shoe	300	Front Attachment	PAT
Appearance			
Engine Cover	Rusted / Corroded	Side Covers	Rusted / Corroded
Under Covers	Rusted / Corroded	Main Frame	Rusted / Corroded
Track Frame	Rusted / Corroded	Lift (Push) Arm	Rusted / Corroded
Cabin	Rusted / Corroded		
Interior			
Seat	Good Condition	Console	Good Condition
Operation			
Engine	Normal	Exhaust Gas Color	Normal
Traveling	Normal	Transmission / Torque Converter	Normal
Steering	Normal	Front Attachment	Normal
Front & Pins			
Wear: Front Pins	Moderate / within Service Limit	Wear / Deformation: Blade	Good
Wear: Tooth / Cutting Edges	Slight		
Undercarriage / Chassis / Tires			
Seize: Track Links	No	Wear: Track Link Extension (Right)	Slight
Wear: Track Link Extension (Left)	Slight	Wear: Track Link Tread (Right)	Slight
Wear: Track Link Tread (Left)	Slight	Wear: Track Link Pins & Bushings (Right)	Slight
Wear: Track Link Pins & Bushings (Left)	Slight	Wear: Track Shoe / Rubber Shoe	Slight
Bent / Broken / Missing: Track Shoe	No	Wear: Upper Rollers	Moderate / within Service Limit
Wear: Lower Rollers	Moderate / within Service Limit	Oil Leak: Rollers	None
Broken / Missing: Rollers	None	Wear: Front Idler (Right)	Moderate / within Service Limit
Wear: Front Idler (Left)	Moderate / within Service Limit	Wear: Sprocket (Right)	Moderate / within Service Limit
Wear: Sprocket (Left)	Moderate / within Service Limit		
Oil / Water / Air Leakage			
Oil Leak: Front Pipes	None	Oil Leak: Lift Cylinder (Right)	None
Oil Leak: Lift Cylinder (Left)	None	Oil Leak: Tilt Cylinder (Right)	None
Oil Leak: Tilt Cylinder (Left)	None	Oil Leak: Angle Cylinder	None
Oil Leak: Engine	Slight Film	Oil Leak: Oil Cooler	None
Leak: Radiator	None	Leak: Cooling Pipes	None
Oil Leak: Fuel System	Slight Film	Oil Leak: Control Valve	Slight Film

Oil Leak: Low Pressure Pipes	Slight Film	Oil Leak: High Pressure Pipes	Slight Film
Oil Leak: Pump Device	Slight Film	Oil Leak: Transmission / Torcon	Slight Film
Overall Rating			
Appearance Evaluation	Fair	Rust / Corrosion	Moderate / within Service Limit
Overall Rating	Fair		