

2004 Hitachi EX20UR-3 Mini Excavator

Basic information			
Model	EX20UR-3	Serial No.	5289
Product category	Mini Excavator	Manufacturer	Hitachi
Year of manufacture	2004	Working hours	4104 hours
Engine No.			
Detail Information			
Job Status	Rental	Cabin / Canopy	Canopy
Front Attachment	Offset	Type of Shoe	Grouser with Pad
Width of Track Shoe	250	Bucket Attachment	Standard
Other	Multi Lever		
Appearance			
Engine Cover	Good Condition	Side Covers	Deformed / Dent
Under Covers	Good Condition	Counter Weight	Good Condition
Main Frame	Good Condition	Track Frame	Good Condition
Cabin	Good Condition		
Interior			
Cabin Interior	Good Condition	Seat	Torn
Console	Good Condition		
Operation			
Engine	Normal	Exhaust Gas Color	Normal
Swing	Normal	Wear: Swing Bearing	Slight
Traveling	Normal	Front Attachment	Normal
Front & Pins			
Boom	Normal	Arm	Deformed / Dent
Wear: Boom Foot Pin	Moderate / within Service Limit	Wear: Boom / Arm Joint Pin	Moderate / within Service Limit
Wear: Arm Tip Pin	Moderate / within Service Limit	Wear: Other Pins	Moderate / within Service Limit
Wear / Deformation: Bucket	Wear: Moderate / within Service Limit	Wear / Deformation: Blade	Wear: Moderate / within Service Limit
Undercarriage / Chassis / Tires			
Seize: Track Links	No	Wear: Track Link Stretching (Right)	Moderate
Wear: Track Link Stretching (Left)	Moderate	Wear: Track Link Tread (Right)	Moderate / within Service Limit
Wear: Track Link Tread (Left)	Moderate / within Service Limit	Wear: Track Link Pins & Bushings (Right)	Moderate / within Service Limit
Wear: Track Link Pins & Bushings (Left)	Moderate / within Service Limit	Wear: Track Shoe / Rubber Shoe	Moderate / within Service Limit
Bent / Broken / Missing: Track Shoe	No	Wear: Rubber Pad	Excessive / Required to replace
Broken / Missing: Rubber Pad	No	Missing: Rubber Pad	No
Wear: Lower Rollers	Moderate / within Service Limit	Oil Leak: Rollers	None
Broken / Missing: Rollers	None	Wear: Front Idler (Right)	Moderate / within Service Limit
Wear: Front Idler (Left)	Moderate / within Service Limit	Wear: Sprocket (Left)	Moderate / within Service Limit
Oil Leak: Travel Device	None	Oil Leak: Travel Pipes	None
Oil / Water / Air Leakage			
Oil Leak: Front Pipes	None	Oil Leak: Boom Cylinder	None
Oil Leak: Arm Cylinder	None	Oil Leak: Bucket Cylinder	None
Oil Leak: Offset Cylinder	None	Oil Leak: Blade Cylinder	None
Oil Leak: Engine	None	Oil Leak: Oil Cooler	None
Leak: Radiator	None	Leak: Cooling Pipes	None

Oil Leak: Fuel System	None	Oil Leak: Upper Structure	None
Oil Leak: Under Carriage	None	Oil Leak: Pilot Pipes	None
Oil Leak: Pilot Valve	None	Oil Leak: Pump Device	None
Overall Rating			
Appearance Evaluation	Fair	Rust / Corrosion	No
Overall Rating	Fair		