

1900 HINO FD176B Dump Truck

Basic information			
Model	FD176B	Serial No.	10060
Product category	Dump Truck	Manufacturer	HINO
Year of manufacture	1900	Working hours	99999 hours
Engine No.	H07C-A10280		
Detail Information			
Power Transmission System	Direct Drive	Front tire	2
Crane performance	2.90	Loading platform type	3-side tipper truck, Flat carrier
Documents	Unknown	License Number Plate	No
Main Frame	Rusted / Corroded		
Appearance			
Cover	Deformed / Dent, Damaged	Cabin / Driving seat	Deformed / Dent, Rusted / Corroded
Door	Good Condition	Cabin Interior	Torn, Damaged
Interior			
Seat	Torn	Console	Malfunction
Air Conditioner	Malfunction	Oil Leak: Travel Device	No
Operation			
Scratches: Tire (Front-Right Wheel)	Moderate / within Service Limit	Scratches: Tire (Rear-Right Wheel)	Moderate / within Service Limit
Scratches: Tire (Front-Left Wheel)	Moderate / within Service Limit	Scratches: Tire (Rear-Left Wheel)	Moderate / within Service Limit
Wear: Tire (Front-Right wheel)	Moderate / within Service Limit	Wear: Tire (Front-Left Wheel)	Moderate / within Service Limit
Wear: Tire (Rear-Right Wheel)	Excessive / Required to replace	Wear: Tire (Rear-Left Wheel)	Excessive / Required to replace
Oil Leak: Axle	No	Oil Leak: Differential Gear Case	No
Undercarriage / Chassis / Tires			
Oil Leak: Oil Cooler	No	Leak: Radiator	No
Leak: Cooling Pipes	Slight Film	Oil Leak: Fuel System	Slight Film
Oil Leak: Control Valve	No	Oil Leak: Low Pressure Pipes	Slight Film, Moderate Oozing
Oil / Water / Air Leakage			
Pump Device	Slight Film, Moderate Oozing	Transmission / Torque Converter	No
Engine	Normal	Exhaust Gas Color	Normal
Traveling	Normal	Transmission / Torque Converter	Normal
Steering	Normal	Gearshift	Normal
Break	Normal	Oil Leak: Engine	Slight Film
Side Break	Normal	Crane	Normal
Other working device	Normal		
?? ? ??			
Vessel	Deformation: Moderate, Repair Mark		
Overall Rating			
Appearance Evaluation	Poor	Rust / Corrosion	Heavy
Overall Rating	Usable		