

1987 Kobelco SK04-2 Hydraulic Excavator

Basic information			
Model	SK04-2	Serial No.	LW-08426
Product category	Hydraulic Excavator	Manufacturer	Kobelco
Year of manufacture	1987	Working hours	1534 hours
Engine No.			
Detail Information			
Job Status	Civil Engineering	Cabin / Canopy	Cabin
Cabin Type	Standard	Front Attachment	Straight Boom, Telescopic Arm
Type of Shoe	Grouser	Width of Track Shoe	500
Bucket Attachment	without Bucket	Other	Piping, Heater
Appearance			
Engine Cover	Deformed / Dent	Side Covers	Deformed / Dent
Counter Weight	Scratched	Main Frame	Good Condition
D Frame	Rusted / Corroded	Track Frame	Good Condition
Cabin	Rusted / Corroded	Door	Stiff Hinges
Interior			
Cabin Interior	Defect / Missing	Seat	Torn
Console	Malfunction		
Operation			
Engine	Normal	Exhaust Gas Color	Normal
Swing	Normal	Wear: Swing Bearing	Moderate / within Service Limit
Traveling	Meandering (Left)	Front Attachment	Normal
Pump Device	Normal		
Front & Pins			
Boom	Normal	Arm	Normal
Wear: Boom Foot Pin	Moderate / within Service Limit	Wear: Boom / Arm Joint Pin	Moderate / within Service Limit
Undercarriage / Chassis / Tires			
Seize: Track Links	No	Wear: Track Link Stretching (Right)	Moderate
Wear: Track Link Stretching (Left)	Moderate	Wear: Track Link Tread (Right)	Moderate / within Service Limit
Wear: Track Link Tread (Left)	Moderate / within Service Limit	Wear: Track Link Pins & Bushings (Right)	Moderate / within Service Limit
Wear: Track Link Pins & Bushings (Left)	Moderate / within Service Limit	Wear: Track Shoe / Rubber Shoe	Excessive / Required to replace
Bent / Broken / Missing: Track Shoe	No	Wear: Upper Rollers	Moderate / within Service Limit
Wear: Lower Rollers	Moderate / within Service Limit	Oil Leak: Rollers	1 - 4 Pieces
Broken / Missing: Rollers	None	Wear: Front Idler (Right)	Moderate / within Service Limit
Wear: Front Idler (Left)	Moderate / within Service Limit	Wear: Sprocket (Right)	Moderate / within Service Limit
Wear: Sprocket (Left)	Moderate / within Service Limit	Oil Leak: Travel Device	None
Oil Leak: Travel Pipes	None		
Oil / Water / Air Leakage			
Oil Leak: Front Pipes	None	Oil Leak: Boom Cylinder (Right)	None
Oil Leak: Boom Cylinder (Left)	None	Oil Leak: Arm Cylinder (Right)	None
Oil Leak: Engine	Slight Film	Oil Leak: Oil Cooler	None
Leak: Radiator	None	Leak: Cooling Pipes	None
Oil Leak: Fuel System	Moderate Oozing	Oil Leak: Control Valve	None

Oil Leak: Low Pressure Pipes	Moderate Oozing	Oil Leak: High Pressure Pipes	None
Oil Leak: Pilot Pipes	None	Oil Leak: Pilot Valve	None
Oil Leak: Center Joint	Moderate Oozing	Oil Leak: Swing Device	Moderate Oozing
Oil Leak: Pump Device	None		
Overall Rating			
Appearance Evaluation	Poor	Rust / Corrosion	Heavy
Overall Rating	Usable		