

1996 Hitachi LX70-2C Wheel Loader

Basic information			
Model	LX70-2C	Serial No.	3173
Product category	Wheel Loader	Manufacturer	Hitachi
Year of manufacture	1996	Working hours	17989 hours
Engine No.			
Detail Information			
Job Status	Others	Type of Tire	Normal
License Plate	No	Cabin / Canopy	Cabin
Power Transmission System	HST	Drive System	All Wheel Drive
Size of Tire	16.9-24-10PR	Bucket Attachment	Loading BK
Appearance			
Main Frame	Rusted / Corroded	Front Frame	Rusted / Corroded
Counter Weight	Scratched	Cabin	Rusted / Corroded
Door	Good Condition		
Interior			
Cabin Interior	Good Condition	Seat	Burned by Cigarette
Console	Malfunction		
Operation			
Engine	Normal	Exhaust Gas Color	Normal
Traveling	Normal	HST Motor	Normal
Front Attachment	Normal	Pump Device	Normal
Steering	Normal	Break	Normal
Side Break	Malfunction		
Front & Pins			
Lift(Push)Arm	Normal	Bellcrank	Normal
Wear: Front Pins & Bushings	Moderate / within Service Limit	Wear: Bucket Pins & Bushings	Moderate / within Service Limit
Wear: Center Pins	Moderate / within Service Limit	Wear: Bucket Side Plate	Slight
Wear: Bucket Lip	Slight	Wear: Bucket Bottom Plate	Slight
Wear: Tooth / Cutting Edges	Moderate / within Service Limit		
Undercarriage / Chassis / Tires			
Scratches: Tire (Front-Right Wheel)	Slight	Wear: Tire (Front-Right wheel)	Moderate / within Service Limit
Scratches: Tire (Front-Left Wheel)	Slight	Wear: Tire (Front-Left Wheel)	Excessive / Required to replace
Scratches: Tire (Rear-Right Wheel)	Slight	Wear: Tire (Rear-Right Wheel)	Moderate / within Service Limit
Scratches: Tire (Rear-Left Wheel)	Slight	Wear: Tire (Rear-Left Wheel)	Moderate / within Service Limit
Oil Leak: Axle	No	Oil Leak: Differential Gear Case	No
Oil / Water / Air Leakage			
Oil Leak: Front Pipes	None	Oil Leak: Lift Cylinder (Right)	Excessive / Required to Repair
Oil Leak: Lift Cylinder (Left)	None	Oil Leak: Bucket Cylinder	None
Oil Leak: Steering Cylinder	Moderate Oozing	Oil Leak: Engine	Slight Film
Oil Leak: Oil Cooler	None	Leak: Radiator	None
Leak: Cooling Pipes	None	Oil Leak: Fuel System	Slight Film

Oil Leak: Control Valve	None	Oil Leak: Low Pressure Pipes	None
Oil Leak: High Pressure Pipes	None	Oil Leak: Pilot Pipes	None
Oil Leak: Pilot Valve	None	Oil Leak: Pump Device	Slight Film
Oil Leak: Transmission / Torcon	Slight Film		
Overall Rating			
Appearance Evaluation	Poor	Rust / Corrosion	Moderate / within Service Limit
Overall Rating	Usable		