

2006 Komatsu PC20UU-3 Mini Excavator

Basic information			
Model	PC20UU-3	Serial No.	11950
Product category	Mini Excavator	Manufacturer	Komatsu
Year of manufacture	2006	Working hours	4520 hours
Engine No.			
Detail Information			
Job Status	Rental	Cabin / Canopy	Canopy
Cabin Type	Standard	Front Attachment	Offset
Type of Shoe	Rubber	Width of Track Shoe	250
Bucket Attachment	Standard		
Appearance			
Engine Cover	Good Condition	Side Covers	Deformed / Dent
Under Covers	Good Condition	Counter Weight	Scratched
Main Frame	Good Condition	Track Frame	Good Condition
Cabin	Deformed / Dent		
Interior			
Seat	Torn	Console	Good Condition
Operation			
Engine	Normal	Exhaust Gas Color	Normal
Swing	Normal	Wear: Swing Bearing	Moderate / within Service Limit
Traveling	Normal	Front Attachment	Normal
Front & Pins			
Boom	Cracked	Arm	Deformed / Dent
Wear: Boom Foot Pin	Moderate / within Service Limit	Wear: Boom / Arm Joint Pin	Moderate / within Service Limit
Wear: Arm Tip Pin	Moderate / within Service Limit	Wear: Other Pins	Moderate / within Service Limit
Wear / Deformation: Bucket	Wear: Moderate / within Service Limit	Wear / Deformation: Blade	Deformation: Moderate
Undercarriage / Chassis / Tires			
Wear: Track Shoe / Rubber Shoe	Moderate / within Service Limit	Broken / Crack: Rubber Shoe (Right)	Some Tears
Broken / Crack: Rubber Shoe (Left)	Some Tears	Missing: Rubber Shoe Core	No
Wear: Lower Rollers	Moderate / within Service Limit	Oil Leak: Rollers	None
Broken / Missing: Rollers	None	Wear: Front Idler (Right)	Moderate / within Service Limit
Wear: Front Idler (Left)	Moderate / within Service Limit	Wear: Sprocket (Right)	Moderate / within Service Limit
Wear: Sprocket (Left)	Moderate / within Service Limit	Oil Leak: Travel Device	None
Oil Leak: Travel Pipes	None		
Oil / Water / Air Leakage			
Oil Leak: Front Pipes	None	Oil Leak: Boom Cylinder	None
Oil Leak: Arm Cylinder	None	Oil Leak: Bucket Cylinder	None
Oil Leak: Offset Cylinder	None	Oil Leak: Blade Cylinder	None
Oil Leak: Engine	None	Oil Leak: Oil Cooler	None
Leak: Radiator	None	Leak: Cooling Pipes	None
Oil Leak: Fuel System	None	Oil Leak: Upper Structure	None
Oil Leak: Under Carriage	None	Oil Leak: Pilot Pipes	None
Oil Leak: Pilot Valve	None	Oil Leak: Pump Device	None
Overall Rating			
Appearance Evaluation	Fair	Rust / Corrosion	Moderate / within Service Limit
Overall Rating	Usable		