

1997 Others FL302-2 Wheel Loader

Basic information			
Model	FL302-2	Serial No.	5030
Product category	Wheel Loader	Manufacturer	Others
Year of manufacture	1997	Working hours	2339 hours
Engine No.			
Detail Information			
Job Status	Rental	Type of Tire	Normal
License Plate	No	Cabin / Canopy	Canopy
Power Transmission System	HST	Drive System	All Wheel Drive
Size of Tire	12.5/70-16-6PR	Bucket Attachment	Loading BK
Appearance			
Main Frame	Rusted / Corroded	Front Frame	Rusted / Corroded
Counter Weight	Scratched	Cabin	Rusted / Corroded
Interior			
Seat	Good Condition	Console	Malfunction
Operation			
Engine	Normal	Exhaust Gas Color	Normal
Traveling	Normal	HST Motor	Normal
Front Attachment	Normal	Pump Device	Normal
Steering	Normal	Break	Poor Operation
Side Break	Normal		
Front & Pins			
Lift(Push)Arm	Normal	Bellcrank	Normal
Wear: Front Pins & Bushings	Slight	Wear: Bucket Pins & Bushings	Slight
Wear: Center Pins	Moderate / within Service Limit	Wear: Bucket Side Plate	Moderate / within Service Limit
Wear: Bucket Lip	Moderate / within Service Limit	Wear: Bucket Bottom Plate	Moderate / within Service Limit
Wear: Tooth / Cutting Edges	Moderate / within Service Limit		
Undercarriage / Chassis / Tires			
Scratches: Tire (Front-Right Wheel)	Moderate / within Service Limit	Wear: Tire (Front-Right wheel)	Moderate / within Service Limit
Scratches: Tire (Front-Left Wheel)	Moderate / within Service Limit	Wear: Tire (Front-Left Wheel)	Moderate / within Service Limit
Scratches: Tire (Rear-Right Wheel)	Moderate / within Service Limit	Wear: Tire (Rear-Right Wheel)	Moderate / within Service Limit
Scratches: Tire (Rear-Left Wheel)	Moderate / within Service Limit	Wear: Tire (Rear-Left Wheel)	Moderate / within Service Limit
Oil Leak: Axle	No	Oil Leak: Differential Gear Case	No
Oil / Water / Air Leakage			
Oil Leak: Front Pipes	None	Oil Leak: Lift Cylinder (Right)	None
Oil Leak: Lift Cylinder (Left)	None	Oil Leak: Bucket Cylinder	None
Oil Leak: Steering Cylinder	None	Oil Leak: Engine	Slight Film
Oil Leak: Oil Cooler	None	Leak: Radiator	None
Leak: Cooling Pipes	None	Oil Leak: Fuel System	Slight Film
Oil Leak: Control Valve	None	Oil Leak: Low Pressure Pipes	None

Oil Leak: High Pressure Pipes	None	Oil Leak: Pilot Pipes	None
Oil Leak: Pilot Valve	None	Oil Leak: Pump Device	Slight Film
Overall Rating			
Appearance Evaluation	Repainted	Rust / Corrosion	Slight
Overall Rating	Usable		