

## 2013 Hitachi ZX20U Mini Excavator

Basic information			
Model	ZX20U	Serial No.	10861
Product category	Mini Excavator	Manufacturer	Hitachi
Year of manufacture	2013	Working hours	1336 hours
Engine No.			
Detail Information			
Job Status	Rental	Cabin / Canopy	Canopy
Front Attachment	Standard	Type of Shoe	Grouser with Pad
Width of Track Shoe	250	Bucket Attachment	Standard
Other	Piping, EPA, Multi Lever		
Appearance			
Engine Cover	Good Condition	Side Covers	Good Condition
Under Covers	Good Condition	Counter Weight	Good Condition
Main Frame	Good Condition	Track Frame	Good Condition
Cabin	Good Condition	Door	Good Condition
Interior			
Cabin Interior	Good Condition	Seat	Good Condition
Console	Good Condition		
Operation			
Engine	Normal	Exhaust Gas Color	Normal
Swing	Normal	Wear: Swing Bearing	Slight
Traveling	Normal	Front Attachment	Normal
Front & Pins			
Boom	Normal	Arm	Normal
Wear: Boom Foot Pin	Slight	Wear: Boom / Arm Joint Pin	Slight
Wear: Arm Tip Pin	Slight	Wear: Other Pins	Slight
Wear / Deformation: Bucket	Wear: Moderate / within Service Limit	Wear / Deformation: Blade	Wear: Moderate / within Service Limit
Undercarriage / Chassis / Tires			
Seize: Track Links	No	Wear: Track Link Stretching (Right)	Slight
Wear: Track Link Stretching (Left)	Slight	Wear: Track Link Tread (Right)	Slight
Wear: Track Link Tread (Left)	Slight	Wear: Track Link Pins & Bushings (Right)	Slight
Wear: Track Link Pins & Bushings (Left)	Slight	Wear: Track Shoe / Rubber Shoe	Slight
Bent / Broken / Missing: Track Shoe	No	Wear: Rubber Pad	Moderate / within Service Limit
Broken / Missing: Rubber Pad	No	Missing: Rubber Pad	No
Wear: Upper Rollers	Slight	Wear: Lower Rollers	Slight
Oil Leak: Rollers	None	Broken / Missing: Rollers	None
Wear: Front Idler (Right)	Slight	Wear: Front Idler (Left)	Slight
Wear: Sprocket (Right)	Slight	Wear: Sprocket (Left)	Slight
Oil Leak: Travel Device	None	Oil Leak: Travel Pipes	None
Oil / Water / Air Leakage			
Oil Leak: Front Pipes	None	Oil Leak: Boom Cylinder	None
Oil Leak: Arm Cylinder	None	Oil Leak: Bucket Cylinder	None
Oil Leak: Swing Cylinder	None	Oil Leak: Blade Cylinder	None
Oil Leak: Engine	None	Oil Leak: Oil Cooler	None

Leak: Radiator	None	Leak: Cooling Pipes	None
Oil Leak: Fuel System	None	Oil Leak: Upper Structure	None
Oil Leak: Under Carriage	None	Oil Leak: Pilot Pipes	None
Oil Leak: Pilot Valve	None	Oil Leak: Pump Device	None
Overall Rating			
Appearance Evaluation	Good	Rust / Corrosion	No
Overall Rating	Good		