

2010 TCM L13-3 Wheel Loader

Basic information			
Model	L13-3	Serial No.	RYU4F000A00008246
Product category	Wheel Loader	Manufacturer	TCM
Year of manufacture	2010	Working hours	3841 hours
Engine No.			
Detail Information			
Job Status	Civil Engineering	Type of Tire	Normal
Documents	Available	Cabin / Canopy	Cabin
Cabin Type	Standard	Power Transmission System	HST
Drive System	All Wheel Drive	Size of Tire	16.9-24-10PR
Bucket Attachment	Loading BK	Other	Air Conditioner
Appearance			
Main Frame	Good Condition	Front Frame	Good Condition
Counter Weight	Scratched	Cabin	Good Condition
Door	Good Condition		
Interior			
Cabin Interior	Defect / Missing	Seat	Torn
Console	Good Condition	Air Conditioner	Good
Operation			
Engine	Normal	Exhaust Gas Color	Normal
Traveling	Normal	Transmission / Torque Converter	Normal
HST Motor	Normal	Front Attachment	Normal
Pump Device	Normal	Steering	Normal
Break	Normal	Side Break	Normal
Front & Pins			
Lift(Push)Arm	Normal	Bellcrank	Normal
Wear: Front Pins & Bushings	Moderate / within Service Limit	Wear: Bucket Pins & Bushings	Moderate / within Service Limit
Wear: Center Pins	Moderate / within Service Limit	Wear: Bucket Side Plate	Moderate / within Service Limit
Wear: Bucket Lip	Moderate / within Service Limit	Wear: Bucket Bottom Plate	Moderate / within Service Limit
Wear: Tooth / Cutting Edges	Moderate / within Service Limit		
Undercarriage / Chassis / Tires			
Scratches: Tire (Front-Right Wheel)	Slight	Wear: Tire (Front-Right wheel)	Moderate / within Service Limit
Scratches: Tire (Front-Left Wheel)	Slight	Wear: Tire (Front-Left Wheel)	Moderate / within Service Limit
Scratches: Tire (Rear-Right Wheel)	Moderate / within Service Limit	Wear: Tire (Rear-Right Wheel)	Excessive / Required to replace
Scratches: Tire (Rear-Left Wheel)	Moderate / within Service Limit	Wear: Tire (Rear-Left Wheel)	Excessive / Required to replace
Oil Leak: Axle	No	Oil Leak: Differential Gear Case	No
Oil / Water / Air Leakage			
Oil Leak: Front Pipes	None	Oil Leak: Lift Cylinder (Right)	None
Oil Leak: Lift Cylinder (Left)	None	Oil Leak: Bucket Cylinder	None
Oil Leak: Steering Cylinder	None	Oil Leak: Engine	Slight Film
Oil Leak: Oil Cooler	None	Leak: Radiator	None

Leak: Cooling Pipes	None	Oil Leak: Fuel System	None
Oil Leak: Control Valve	None	Oil Leak: Low Pressure Pipes	None
Oil Leak: High Pressure Pipes	None	Oil Leak: Pilot Pipes	None
Oil Leak: Pilot Valve	None	Oil Leak: Pump Device	None
Oil Leak: Transmission / Torcon	None		
Overall Rating			
Appearance Evaluation	Fair	Rust / Corrosion	Moderate / within Service Limit
Overall Rating	Fair		