

# 1984 Kobelco SK04WS Wheel Excavator

Basic information			
Model	SK04WS	Serial No.	YD-00291
Product category	Wheel Excavator	Manufacturer	Kobelco
Year of manufacture	1984	Working hours	5118 hours
Engine No.			
Detail Information			
Job Status	Civil Engineering	Cabin Type	Standard
Front Attachment	Standard	License Number Plate	No
Bucket Attachment	Slope Finishing	Drive System	Rear Drive
Type of Tire	Double	Size of Tire	9.00-20-14PR
Appearance			
Engine Cover	Rusted / Corroded	Side Covers	Rusted / Corroded
Under Covers	Rusted / Corroded	Counter Weight	Scratched
Main Frame	Rusted / Corroded	D Frame	Rusted / Corroded
Shassis	Rusted / Corroded	Cabin	Rusted / Corroded
Door	Good Condition		
Interior			
Cabin Interior	Torn	Seat	Torn
Console	Malfunction		
Operation			
Engine	Normal	Exhaust Gas Color	White Smoke
Swing	Normal	Wear: Swing Bearing	Slight
Traveling	Normal	Front Attachment	Normal
Outrigger	Normal	Steering	Normal
Break	Normal	Side Break	Normal
Pump Device	Normal		
Front & Pins			
Boom	Deformed / Dent	Arm	Deformed / Dent
Wear: Boom Foot Pin	Moderate / within Service Limit	Wear: Boom / Arm Joint Pin	Moderate / within Service Limit
Wear: Arm Tip Pin	Moderate / within Service Limit	Wear / Deformation: Bucket	Wear: Moderate / within Service Limit
Undercarriage / Chassis / Tires			
Scratches: Tire (Front-Right Wheel)	Moderate / within Service Limit	Wear: Tire (Front-Right wheel)	Excessive / Required to replace
Scratches: Tire (Front-Left Wheel)	Moderate / within Service Limit	Wear: Tire (Front-Left Wheel)	Excessive / Required to replace
Scratches: Tire (Rear-Right Wheel)	Moderate / within Service Limit	Wear: Tire (Rear-Right Wheel)	Moderate / within Service Limit
Scratches: Tire (Rear-Left Wheel)	Moderate / within Service Limit	Wear: Tire (Rear-Left Wheel)	Moderate / within Service Limit
Oil Leak: Axle	No	Oil Leak: Differential Gear Case	No
Oil Leak: Steering Cylinder	Slight Film		
Oil / Water / Air Leakage			
Oil Leak: Front Pipes	None	Oil Leak: Boom Cylinder (Right)	Moderate Oozing
Oil Leak: Boom Cylinder (Left)	Slight Film	Oil Leak: Arm Cylinder	None
Oil Leak: Bucket Cylinder	Slight Film	Oil Leak: Outrigger Cylinder	None
Oil Leak: Engine	None	Oil Leak: Oil Cooler	None
Leak: Radiator	None	Leak: Cooling Pipes	None
Oil Leak: Fuel System	None	Compressor	Normal

Oil Leak: Control Valve	None	Oil Leak: Low Pressure Pipes	None
Oil Leak: High Pressure Pipes	None	Oil Leak: Pilot Pipes	None
Oil Leak: Pilot Valve	None	Oil Leak: Center Joint	None
Oil Leak: Swing Device	None	Oil Leak: Pump Device	None
Overall Rating			
Appearance Evaluation	Poor	Rust / Corrosion	Moderate / within Service Limit
Overall Rating	Fair		