

1993 Sakai TW500P Roller

| Basic information | | | |
|-------------------------------------|---------------------------------|--|---------------------------------|
| Model | TW500P | Serial No. | 10114 |
| Product category | Roller | Manufacturer | Sakai |
| Year of manufacture | 1993 | Working hours | 3693 hours |
| Engine No. | | | |
| Detail Information | | | |
| Power Transmission System | HST | Drive System | All Wheel Drive |
| Appearance | | | |
| Main Frame | Rusted / Corroded | | |
| Interior | | | |
| Seat | Good Condition | Console | Good Condition |
| Operation | | | |
| Wear / Scratches: Tire (Rear Wheel) | Moderate / within Service Limit | Wear / Scratches: Tire (Front Iron-Wheel) | Moderate / within Service Limit |
| Wear / Broken: brush (Front wheel) | Excessive / Required to replace | Wear / Broken: brush (Rear wheel) | Excessive / Required to replace |
| Oil Leak: Travel Device | No | Oil Leak: Travel Pipes | No |
| Vibration motor pipes | No | Broken / Crack: Vibration motor vibration-proof rubber | Exist |
| Oil / Water / Air Leakage | | | |
| Oil Leak: Steering Cylinder | No | Oil Leak: Engine | Slight Film |
| Pump Device | Slight Film | Engine | Normal |
| Exhaust Gas Color | Normal | Traveling | Normal |
| Vibrating device | Weak | Break | Normal |
| Side Break | Normal | Wear: Center Pins | Moderate / within Service Limit |
| Undercarriage / Chassis / Tires | | | |
| Oil Leak: Oil Cooler | No | Leak: Radiator | No |
| Leak: Cooling Pipes | No | Oil Leak: Fuel System | No |
| Oil Leak: Control Valve | No | Oil Leak: Low Pressure Pipes | No |
| Oil Leak: High Pressure Pipes | No | | |
| Overall Rating | | | |
| Appearance Evaluation | Repainted | Rust / Corrosion | Moderate / within Service Limit |
| Overall Rating | Usable | | |