

1900 Others BD2 Bulldozer/Tractor Shovel

Basic information			
Model	BD2	Serial No.	8774
Product category	Bulldozer/Tractor Shovel	Manufacturer	Others
Year of manufacture	1900	Working hours	99999 hours
Engine No.			
Detail Information			
Job Status	General Contractor / Civil Engineering	Cabin / Canopy	Canopy
Power Transmission System	Direct Drive	Type of Shoe	Grouser
Width of Track Shoe	300	Front Attachment	Straight Tilt
Appearance			
Engine Cover	Rusted / Corroded	Side Covers	Rusted / Corroded
Under Covers	Rusted / Corroded	Main Frame	Rusted / Corroded
Track Frame	Rusted / Corroded	Lift (Push) Arm	Rusted / Corroded
Cabin	Rusted / Corroded		
Interior			
Seat	Good Condition	Console	Good Condition
Operation			
Engine	Normal	Exhaust Gas Color	White Smoke
Traveling	Normal	Transmission / Torque Converter	Normal
Clutch	Normal	Steering	Normal
Front Attachment	Normal		
Front & Pins			
Wear: Front Pins	Moderate / within Service Limit	Wear / Deformation: Blade	Wear: Moderate / within Service Limit
Wear: Tooth / Cutting Edges	Moderate / within Service Limit		
Undercarriage / Chassis / Tires			
Seize: Track Links	No	Wear: Track Link Extension (Right)	Slight
Wear: Track Link Extension (Left)	Slight	Wear: Track Link Tread (Right)	Moderate / within Service Limit
Wear: Track Link Tread (Left)	Moderate / within Service Limit	Wear: Track Link Pins & Bushings (Right)	Moderate / within Service Limit
Wear: Track Link Pins & Bushings (Left)	Moderate / within Service Limit	Wear: Track Shoe / Rubber Shoe	Excessive / Required to replace
Bent / Broken / Missing: Track Shoe	More than 10 Pieces	Wear: Lower Rollers	Moderate / within Service Limit
Oil Leak: Rollers	None	Broken / Missing: Rollers	None
Wear: Front Idler (Right)	Moderate / within Service Limit	Wear: Front Idler (Left)	Moderate / within Service Limit
Wear: Sprocket (Right)	Slight	Wear: Sprocket (Left)	Slight
Oil / Water / Air Leakage			
Oil Leak: Front Pipes	None	Oil Leak: Lift Cylinder (Right)	Slight Film
Oil Leak: Lift Cylinder (Left)	Slight Film	Oil Leak: Engine	Slight Film
Oil Leak: Oil Cooler	None	Leak: Radiator	None
Leak: Cooling Pipes	None	Oil Leak: Fuel System	None
Oil Leak: Control Valve	None	Oil Leak: Low Pressure Pipes	None

Oil Leak: High Pressure Pipes	None	Oil Leak: Pump Device	Slight Film
Oil Leak: Transmission / Torcon	Slight Film		
Overall Rating			
Appearance Evaluation	Poor	Rust / Corrosion	Heavy
Overall Rating	Usable		