

2005 Hitachi ZX30U-2 Mini Excavator

Basic information			
Model	ZX30U-2	Serial No.	11161
Product category	Mini Excavator	Manufacturer	Hitachi
Year of manufacture	2005	Working hours	4633 hours
Engine No.			
Detail Information			
Job Status	Rental	Cabin / Canopy	Canopy
Cabin Type	ROPS	Front Attachment	Standard
Type of Shoe	Rubber	Width of Track Shoe	300
Bucket Attachment	Standard	Other	EPA, Multi Lever
Appearance			
Engine Cover	Good Condition	Side Covers	Rusted / Corroded
Under Covers	Rusted / Corroded	Counter Weight	Scratched
Main Frame	Rusted / Corroded	Track Frame	Rusted / Corroded
Cabin	Rusted / Corroded		
Interior			
Seat	Good Condition	Console	Faded
Operation			
Engine	Normal	Exhaust Gas Color	Normal
Swing	Normal	Wear: Swing Bearing	Moderate / within Service Limit
Traveling	Normal	Front Attachment	Normal
Front & Pins			
Boom	Normal	Arm	Reinforcement
Wear: Boom Foot Pin	Moderate / within Service Limit	Wear: Boom / Arm Joint Pin	Moderate / within Service Limit
Wear: Arm Tip Pin	Heavy	Wear: Other Pins	Heavy
Wear / Deformation: Bucket	Deformation: Moderate	Wear / Deformation: Blade	Deformation: Moderate
Undercarriage / Chassis / Tires			
Wear: Track Link Stretching (Right)	Slight	Wear: Track Link Stretching (Left)	Slight
Wear: Track Link Tread (Right)	Moderate / within Service Limit	Wear: Track Link Tread (Left)	Moderate / within Service Limit
Wear: Track Link Pins & Bushings (Right)	Moderate / within Service Limit	Wear: Track Link Pins & Bushings (Left)	Moderate / within Service Limit
Wear: Track Shoe / Rubber Shoe	Moderate / within Service Limit	Broken / Crack: Rubber Shoe (Right)	No
Broken / Crack: Rubber Shoe (Left)	No	Missing: Rubber Shoe Core	No
Wear: Upper Rollers	Moderate / within Service Limit	Wear: Lower Rollers	Moderate / within Service Limit
Oil Leak: Rollers	None	Broken / Missing: Rollers	None
Wear: Front Idler (Right)	Slight	Wear: Front Idler (Left)	Slight
Wear: Sprocket (Right)	Slight	Wear: Sprocket (Left)	Slight
Oil Leak: Travel Device	None	Oil Leak: Travel Pipes	None
Oil / Water / Air Leakage			
Oil Leak: Front Pipes	None	Oil Leak: Boom Cylinder	None
Oil Leak: Arm Cylinder	None	Oil Leak: Bucket Cylinder	None
Oil Leak: Swing Cylinder	None	Oil Leak: Blade Cylinder	None
Oil Leak: Engine	None	Oil Leak: Oil Cooler	None
Leak: Radiator	None	Leak: Cooling Pipes	None
Oil Leak: Fuel System	None	Oil Leak: Upper Structure	None
Oil Leak: Under Carriage	None	Oil Leak: Pilot Pipes	None

Oil Leak: Pilot Valve	None	Oil Leak: Pump Device	None
Overall Rating			
Appearance Evaluation	Repainted	Rust / Corrosion	Moderate / within Service Limit
Overall Rating	Fair		