

2010 Denyo DCA-45ESI Generator/Compressor/Welder/Attachment

Basic information			
Model	DCA-45ESI	Serial No.	3844887
Product category	Generator/Compressor/Welder/Attachment	Manufacturer	Denyo
Year of manufacture	2010	Working hours	1341 hours
Engine No.			
Detail Information			
Type	Generator	Voltage	220
Frequency	60		
Appearance			
Frame	Rusted / Corroded	Cover	Deformed / Dent, Rusted / Corroded
Door	Good Condition		
Oil / Water / Air Leakage			
Oil Leak: Engine	Slight Film	Leak: Cooling Pipes	No
Oil Leak: Fuel System	No	Engine	Normal
Exhaust Gas Color	Normal	Control panel	Normal
Electric generator	Normal		
Undercarriage / Chassis / Tires			
Oil Leak: Oil Cooler	No	Leak: Radiator	No
Overall Rating			
Appearance Evaluation	Poor	Rust / Corrosion	Moderate / within Service Limit
Overall Rating	Fair		