

# 1996 Hitachi EX22-2 Mini Excavator

| Basic information                   |                                       |  |                                       |
|-------------------------------------|---------------------------------------|--|---------------------------------------|
| Model                               | EX22-2                                | Serial No.                               | 2553                                  |
| Product category                    | Mini Excavator                        | Manufacturer                             | Hitachi                               |
| Year of manufacture                 | 1996                                  | Working hours                            | 4990 hours                            |
| Engine No.                          | 052070                                |  |                                       |
| Detail Information                  |                                       |  |                                       |
| Job Status                          | Civil Engineering                     | Cabin / Canopy                           | Canopy                                |
| Cabin Type                          | Standard                              | Front Attachment                         | Standard                              |
| Type of Shoe                        | Rubber                                | Width of Track Shoe                      | 250                                   |
| Bucket Attachment                   | Standard                              |  |                                       |
| Appearance                          |                                       |  |                                       |
| Engine Cover                        | Rusted / Corroded                     | Side Covers                              | Rusted / Corroded                     |
| Under Covers                        | Rusted / Corroded                     | Counter Weight                           | Scratched                             |
| Main Frame                          | Rusted / Corroded                     | Track Frame                              | Rusted / Corroded                     |
| Cabin                               | Rusted / Corroded                     | Door                                     | Good Condition                        |
| Interior                            |                                       |  |                                       |
| Cabin Interior                      | Torn                                  | Seat                                     | Torn                                  |
| Console                             | Faded                                 |  |                                       |
| Operation                           |                                       |  |                                       |
| Engine                              | Normal                                | Exhaust Gas Color                        | Normal                                |
| Swing                               | Normal                                | Wear: Swing Bearing                      | Slight                                |
| Traveling                           | Normal                                | Front Attachment                         | Normal                                |
| Front & Pins                        |                                       |  |                                       |
| Boom                                | Normal                                | Arm                                      | Normal                                |
| Wear: Boom Foot Pin                 | Moderate / within Service Limit       | Wear: Boom / Arm Joint Pin               | Moderate / within Service Limit       |
| Wear: Arm Tip Pin                   | Moderate / within Service Limit       | Wear: Other Pins                         | Moderate / within Service Limit       |
| Wear / Deformation: Bucket          | Wear: Moderate / within Service Limit | Wear / Deformation: Blade                | Wear: Moderate / within Service Limit |
| Undercarriage / Chassis / Tires     |                                       |  |                                       |
| Seize: Track Links                  | No                                    | Wear: Track Link Stretching (Right)      | Slight                                |
| Wear: Track Link Stretching (Left)  | Slight                                | Wear: Track Link Tread (Right)           | Moderate / within Service Limit       |
| Wear: Track Link Tread (Left)       | Moderate / within Service Limit       | Wear: Track Link Pins & Bushings (Right) | Moderate / within Service Limit       |
| Broken / Crack: Rubber Shoe (Right) | No                                    | Broken / Crack: Rubber Shoe (Left)       | No                                    |
| Missing: Rubber Shoe Core           | No                                    | Wear: Lower Rollers                      | Moderate / within Service Limit       |
| Oil Leak: Rollers                   | 1 - 4 Pieces                          | Broken / Missing: Rollers                | None                                  |
| Wear: Front Idler (Right)           | Moderate / within Service Limit       | Wear: Front Idler (Left)                 | Moderate / within Service Limit       |
| Wear: Sprocket (Right)              | Moderate / within Service Limit       | Wear: Sprocket (Left)                    | Moderate / within Service Limit       |
| Oil Leak: Travel Device             | None                                  | Oil Leak: Travel Pipes                   | None                                  |
| Oil / Water / Air Leakage           |                                       |  |                                       |
| Oil Leak: Front Pipes               | None                                  | Oil Leak: Boom Cylinder                  | None                                  |
| Oil Leak: Arm Cylinder              | None                                  | Oil Leak: Bucket Cylinder                | None                                  |
| Oil Leak: Swing Cylinder            | None                                  | Oil Leak: Blade Cylinder                 | None                                  |
| Oil Leak: Engine                    | Slight Film                           | Oil Leak: Oil Cooler                     | None                                  |
| Leak: Radiator                      | None                                  | Leak: Cooling Pipes                      | None                                  |
| Oil Leak: Fuel System               | Slight Film                           | Oil Leak: Upper Structure                | Slight Film                           |
| Oil Leak: Under Carriage            | None                                  | Oil Leak: Pilot Pipes                    | None                                  |
| Oil Leak: Pilot Valve               | None                                  | Oil Leak: Pump Device                    | Slight Film                           |

|                       |        |                  |                                 |
|-----------------------|--------|------------------|---------------------------------|
| Overall Rating        |        |                  |                                 |
| Appearance Evaluation | Poor   | Rust / Corrosion | Moderate / within Service Limit |
| Overall Rating        | Usable |                  |                                 |