

1900 TOYOTA 02-5FD25 Forklift

Basic information			
Model	02-5FD25	Serial No.	5FD25-29219
Product category	Forklift	Manufacturer	TOYOTA
Year of manufacture	1900	Working hours	17591 hours
Engine No.			
Detail Information			
Power Transmission System	Torque Converter	Drive System	Front Drive
Size of Tire (Front)	7.00-12/5.00	Size of Tire (Rear)	6.50-10/5.00
Rear wheel tire	2	Max working height	3
Fuel System	Diesel		
Appearance			
Main Frame	Rusted / Corroded	Mast	Rusted / Corroded
Fin guard	Deformed / Dent, Rusted / Corroded	Engine Cover	Rusted / Corroded
Lever	Rusted / Corroded	Cabin / Canopy	Rusted / Corroded
Interior			
Seat	Torn	Console	Good Condition
Operation			
Scratches: Tire	Excessive / Required to replace	Wear: Tire	Excessive / Required to replace
Oil Leak: Axle	No	Oil Leak: Differential Gear Case	No
Oil Leak: Oil Cooler	No	Leak: Radiator	No
Undercarriage / Chassis / Tires			
Lift cylinder (Right)	No	Oil Leak: Control Valve	Slight Film
Oil Leak: Low Pressure Pipes	Slight Film	Oil Leak: High Pressure Pipes	Slight Film
Pump Device	Slight Film		
Oil / Water / Air Leakage			
Lift cylinder (Left)	No	Oil Leak: Tilt Cylinder (Right)	No
Oil Leak: Tilt Cylinder (Left)	No	Oil Leak: Steering Cylinder	Slight Film
Working machine cylinder (Right)	No	Oil Leak: Engine	Slight Film
Transmission / Torque Converter	No	Engine	Normal
Exhaust Gas Color	White Smoke	Traveling	Normal
Transmission / Torque Converter	Normal	Steering	Normal
Break	Normal	Side Break	Normal
Front Attachment	Normal	Wear: Fork	Wear: Moderate / within Service Limit
Front & Pins			
Leak: Cooling Pipes	No	Oil Leak: Fuel System	No
Overall Rating			
Appearance Evaluation	Poor	Rust / Corrosion	Moderate / within Service Limit
Overall Rating	Usable		