

1996 CAT D4H Bulldozer/Tractor Shovel

Basic information			
Model	D4H	Serial No.	9GJ01737
Product category	Bulldozer/Tractor Shovel	Manufacturer	CAT
Year of manufacture	1996	Working hours	2646 hours
Engine No.	09Z15377		
Detail Information			
Job Status	Others	Cabin / Canopy	Cabin
Cabin Type	Standard	Power Transmission System	Torque Converter
Type of Shoe	Triangle	Width of Track Shoe	760
Front Attachment	PAT	Other	Cooler, Heater
Appearance			
Engine Cover	Rusted / Corroded	Side Covers	Rusted / Corroded
Under Covers	Rusted / Corroded	Main Frame	Rusted / Corroded
Track Frame	Rusted / Corroded	Lift (Push) Arm	Rusted / Corroded
Cabin	Rusted / Corroded	Door	Good Condition
Interior			
Cabin Interior	Torn	Seat	Torn
Console	Faded	Air Conditioner	Good
Operation			
Engine	Normal	Exhaust Gas Color	Normal
Traveling	Normal	Transmission / Torque Converter	Normal
Steering	Normal	Front Attachment	Normal
Front & Pins			
Wear: Front Pins	Moderate / within Service Limit	Wear / Deformation: Blade	Wear: Moderate / within Service Limit
Wear: Tooth / Cutting Edges	Moderate / within Service Limit		
Undercarriage / Chassis / Tires			
Seize: Track Links	No	Wear: Track Link Extension (Right)	Slight
Wear: Track Link Extension (Left)	Slight	Wear: Track Link Tread (Right)	Moderate / within Service Limit
Wear: Track Link Tread (Left)	Moderate / within Service Limit	Wear: Track Link Pins & Bushings (Right)	Moderate / within Service Limit
Wear: Track Link Pins & Bushings (Left)	Moderate / within Service Limit	Wear: Track Shoe / Rubber Shoe	Moderate / within Service Limit
Bent / Broken / Missing: Track Shoe	No	Wear: Upper Rollers	Moderate / within Service Limit
Wear: Lower Rollers	Moderate / within Service Limit	Oil Leak: Rollers	None
Broken / Missing: Rollers	None	Wear: Front Idler (Right)	Moderate / within Service Limit
Wear: Front Idler (Left)	Moderate / within Service Limit	Wear: Rear Idler (Right)	Moderate / within Service Limit
Wear: Rear Idler (Left)	Moderate / within Service Limit	Wear: Sprocket (Right)	Moderate / within Service Limit
Wear: Sprocket (Left)	Moderate / within Service Limit		
Oil / Water / Air Leakage			
Oil Leak: Front Pipes	Slight Film	Oil Leak: Lift Cylinder (Right)	None
Oil Leak: Lift Cylinder (Left)	None	Oil Leak: Tilt Cylinder (Right)	None
Oil Leak: Tilt Cylinder (Left)	None	Oil Leak: Angle Cylinder	None
Oil Leak: Engine	None	Oil Leak: Oil Cooler	None

Leak: Radiator	None	Leak: Cooling Pipes	None
Oil Leak: Fuel System	None	Oil Leak: Control Valve	Slight Film
Oil Leak: Low Pressure Pipes	Slight Film	Oil Leak: High Pressure Pipes	None
Oil Leak: Pump Device	Slight Film	Oil Leak: Transmission / Torcon	None
Oil Leak: Pilot Valve	None	Oil Leak: Pilot Pipes	None
Overall Rating			
Appearance Evaluation	Fair	Rust / Corrosion	Moderate / within Service Limit
Overall Rating	Fair		