

# 1900 Others SK099 Lifting Equipment

Basic information			
Model	SK099	Serial No.	650293
Product category	Lifting Equipment	Manufacturer	Others
Year of manufacture	1900	Working hours	4522 hours
Engine No.			
Detail Information			
Arm type	Straight and flexion type	Underbody	Tire
Drive System	Direct Drive	Chassis manufacturer	MITSUBISHI
License Number Plate	Exist		
Appearance			
Shassis	Rusted / Corroded	Platform	Good Condition
Side Covers	Deformed / Dent, Rusted / Corroded	Door	Good Condition
Interior			
Seat	Good Condition	Console	Good Condition
Air Conditioner	Good Condition		
Oil / Water / Air Leakage			
Transmission / Torque Converter	No	Oil Leak: Boom Cylinder	Moderate Oozing
Telescopic cylinder	No	Oil Leak: Outrigger Cylinder	No
Oil Leak: Engine	Slight Film	Oil Leak: Pilot Valve	No
Oil Leak: Center Joint	No	Oil Leak: Swing Device	No
Pump Device	No	Engine	Normal
Exhaust Gas Color	Normal	Swing	Normal
Traveling	Normal	Front	Normal
Break	Normal	Side Break	Normal
Transmission / Torque Converter	Normal	Clutch	Normal
Safety device	Normal	Wear: Front Pins & Bushings	Moderate / within Service Limit
Undercarriage / Chassis / Tires			
Oil Leak: Differential Gear Case	No	Oil Leak: Axle	No
Scratches: Tire	Moderate / within Service Limit	Wear: Tire	Moderate / within Service Limit
Oil Leak: Front Pipes	No	Oil Leak: Oil Cooler	No
Leak: Radiator	No	Leak: Cooling Pipes	No
Oil Leak: Fuel System	No	Oil Leak: Control Valve	No
Oil Leak: Pilot Pipes	No		
Overall Rating			
Appearance Evaluation	Repainted	Rust / Corrosion	Moderate / within Service Limit
Overall Rating	Usable		