

1998 Morooka MST-800 Carrier

Basic information			
Model	MST-800	Serial No.	2324
Product category	Carrier	Manufacturer	Morooka
Year of manufacture	1998	Working hours	
Engine No.			
Detail Information			
Type of Shoe	Rubber	Loading platform type	Gravel carrier
Main Frame	Rusted / Corroded		
Appearance			
Track Frame	Rusted / Corroded	Front bumper	Deformed / Dent, Rusted / Corroded
Cabin / Canopy	Rusted / Corroded		
Interior			
Seat	Torn	Console	Malfunction
Wear: Track Link Stretching (Right)	Slight		
Operation			
Wear: Track Link Stretching (Left)	Slight	Wear: Track Link Tread (Right)	Slight
Wear: Track Link Tread (Left)	Slight	Broken / Crack: Rubber Shoe (Right)	Slight
Broken / Crack: Rubber Shoe (Left)	Slight	Missing: Rubber Shoe Core	No
Wear: Upper Rollers	Moderate / within Service Limit	Wear: Lower Rollers	Moderate / within Service Limit
Oil Leak: Rollers	No		
Undercarriage / Chassis / Tires			
Wear: Rubber Shoe	Slight	Wear: Pivot shaft	No
Broken / Missing: Rollers	No	Wear: Front Idler (Right)	Slight
Wear: Front Idler (Left)	Slight	Wear: Sprocket (Right)	Slight
Wear: Sprocket (Left)	Slight	Oil Leak: Travel Device	No
Oil Leak: Travel Pipes	No	Oil Leak: Oil Cooler	No
Leak: Radiator	No	Leak: Cooling Pipes	No
Oil Leak: Fuel System	Slight Film	Oil Leak: Control Valve	No
Oil Leak: Low Pressure Pipes	No		
Oil / Water / Air Leakage			
Oil Leak: High Pressure Pipes	No	Pump Device	Slight Film
Engine	Normal	Exhaust Gas Color	White Smoke
Traveling	Normal	Dump cylinder (Right)	Slight Film
Break	Normal	Dump cylinder (Left)	Slight Film
Side Break	Normal	Oil Leak: Engine	Slight Film
Dumping	Normal		
?? ? ??			
Vessel	Deformation: Heavy, Repair Mark	Frame	Deformation: Heavy
Overall Rating			
Appearance Evaluation	Poor	Rust / Corrosion	Heavy
Overall Rating	Usable		