

1981 Others BD2F Bulldozer/Tractor Shovel

Basic information			
Model	BD2F	Serial No.	1B001146
Product category	Bulldozer/Tractor Shovel	Manufacturer	Others
Year of manufacture	1981	Working hours	
Engine No.			
Detail Information			
Job Status	General Contractor / Civil Engineering	Cabin / Canopy	Canopy
Cabin Type	Standard	Power Transmission System	Torque Converter
Type of Shoe	Grouser	Front Attachment	Straight Tilt
Appearance			
Engine Cover	Rusted / Corroded	Side Covers	Rusted / Corroded
Under Covers	Rusted / Corroded	Main Frame	Rusted / Corroded
Track Frame	Rusted / Corroded	Lift (Push) Arm	Rusted / Corroded
Cabin	Rusted / Corroded	Door	Stiff Hinges
Interior			
Cabin Interior	Torn	Seat	Torn
Console	Faded		
Operation			
Engine	Normal	Exhaust Gas Color	Normal
Traveling	Normal	Transmission / Torque Converter	Normal
Clutch	Normal	Steering	Normal
Front Attachment	Normal		
Front & Pins			
Wear: Front Pins	Moderate / within Service Limit	Wear / Deformation: Blade	Deformation: Moderate
Wear: Tooth / Cutting Edges	Moderate / within Service Limit	Wear: Bucket Side Plate	Moderate / within Service Limit
Wear: Bucket Lip	Moderate / within Service Limit	Wear: Bucket Bottom Plate	Moderate / within Service Limit
Undercarriage / Chassis / Tires			
Seize: Track Links	No	Wear: Track Link Extension (Right)	Excessive
Wear: Track Link Extension (Left)	Excessive	Wear: Track Link Tread (Right)	Moderate / within Service Limit
Wear: Track Link Tread (Left)	Moderate / within Service Limit	Wear: Track Link Pins & Bushings (Right)	Moderate / within Service Limit
Wear: Track Link Pins & Bushings (Left)	Moderate / within Service Limit	Wear: Track Shoe / Rubber Shoe	Moderate / within Service Limit
Bent / Broken / Missing: Track Shoe	No	Wear: Upper Rollers	Moderate / within Service Limit
Wear: Lower Rollers	Moderate / within Service Limit	Oil Leak: Rollers	None
Broken / Missing: Rollers	None	Wear: Front Idler (Right)	Moderate / within Service Limit
Wear: Front Idler (Left)	Moderate / within Service Limit	Wear: Sprocket (Right)	Moderate / within Service Limit
Wear: Sprocket (Left)	Moderate / within Service Limit		
Oil / Water / Air Leakage			
Oil Leak: Front Pipes	None	Oil Leak: Lift Cylinder (Right)	Slight Film
Oil Leak: Lift Cylinder (Left)	None	Oil Leak: Engine	Slight Film
Oil Leak: Oil Cooler	None	Leak: Radiator	None
Leak: Cooling Pipes	None	Oil Leak: Fuel System	None

Oil Leak: Control Valve	None	Oil Leak: Low Pressure Pipes	None
Oil Leak: High Pressure Pipes	None	Oil Leak: Pump Device	None
Oil Leak: Transmission / Torcon	None	Oil Leak: Pilot Valve	None
Oil Leak: Pilot Pipes	None		
Overall Rating			
Appearance Evaluation	Fair	Rust / Corrosion	Moderate / within Service Limit
Overall Rating	Fair		