

## 2004 Sakai TW350-1 Roller

| Basic information                   |                |  |  |                 |
|-------------------------------------|----------------|--|--|-----------------|
| Model                               | TW350-1        |  | Serial No.   | 11089           |
| Product category                    | Roller         |  | Manufacturer   | Sakai           |
| Year of manufacture                 | 2004           |  | Working hours  |                 |
| Engine No.                          |                |  |  |                 |
| Detail Information                  |                |  |  |                 |
| Power Transmission System           | HST            |  | Drive System   | All Wheel Drive |
| Appearance                          |                |  |  |                 |
| Main Frame                          | Good Condition |  |  |                 |
| Interior                            |                |  |  |                 |
| Seat                                | Good Condition |  | Console  | Faded           |
| Operation                           |                |  |  |                 |
| Wear / Scratches: Tire (Rear Wheel) | Slight         |  | Wear / Scratches: Tire (Front Iron-Wheel)              | Slight          |
| Oil Leak: Travel Device             | No             |  | Oil Leak: Travel Pipes                                 | No              |
| Vibration motor pipes               | No             |  | Broken / Crack: Vibration motor vibration-proof rubber | No              |
| Oil / Water / Air Leakage           |                |  |  |                 |
| Oil Leak: Steering Cylinder         | No             |  | Oil Leak: Engine                                       | No              |
| Pump Device                         | No             |  | Transmission / Torque Converter                        | No              |
| Engine                              | Normal         |  | Exhaust Gas Color                                      | Normal          |
| Traveling                           | Normal         |  | Transmission / Torque Converter                        | Normal          |
| Vibrating device                    | Normal         |  | Break  | Normal          |
| Side Break                          | Normal         |  | Wear: Center Pins                                      | Slight          |
| Undercarriage / Chassis / Tires     |                |  |  |                 |
| Oil Leak: Oil Cooler                | No             |  | Leak: Radiator   | No              |
| Leak: Cooling Pipes                 | No             |  | Oil Leak: Fuel System                                  | No              |
| Oil Leak: Control Valve             | No             |  | Oil Leak: Low Pressure Pipes                           | No              |
| Oil Leak: High Pressure Pipes       | No             |  | Oil Leak: Pilot Pipes                                  | No              |
| Overall Rating                      |                |  |  |                 |
| Appearance Evaluation               | Fair           |  | Rust / Corrosion                                       | Slight          |
| Overall Rating                      | Fair           |  |  |                 |