## 2006 TCM FD25T3 Forklift

| Basic information               |                   |                                     |                                 |
|---------------------------------|-------------------|-------------------------------------|---------------------------------|
| Model                           | FD25T3            | Serial No.                          | 2N502621                        |
| Product category                | Forklift          | Manufacturer                        | TCM                             |
| Year of manufacture             | 2006              | Working hours                       |                                 |
| Engine No.                      |                   |                                     |                                 |
| Detail Information              |                   |                                     |                                 |
| Power Transmission<br>System    | Torque Converter  | Drive System                        | Front Drive                     |
| Fuel System                     | Diesel            |                                     |                                 |
| Appearance                      |                   |                                     |                                 |
| Main Frame                      | Rusted / Corroded | Mast                                | Rusted / Corroded               |
| Fin guard                       | Rusted / Corroded | Engine Cover                        | Rusted / Corroded               |
| Lever                           | Good Condition    | Cabin / Canopy                      | Rusted / Corroded               |
| Door                            | Good Condition    |                                     |                                 |
| Interior                        |                   |                                     |                                 |
| Seat                            | Good Condition    | Console                             | Good Condition                  |
| Operation                       |                   |                                     |                                 |
| Scratches: Tire                 | Slight            | Wear: Tire                          | Excessive / Required to replace |
| Oil Leak: Axle                  | No                | Oil Leak: Differential Gear<br>Case | No                              |
| Oil Leak: Oil Cooler            | No                | Leak: Radiator                      | No                              |
| Undercarriage / Chassis /       | Tires             |                                     |                                 |
| Lift cylinder (Right)           | No                | Oil Leak: Control Valve             | No                              |
| Oil Leak: Low Pressure<br>Pipes | No                | Oil Leak: High Pressure<br>Pipes    | No                              |
| Oil Leak: Pilot Pipes           | No                | Pump Device                         | No                              |
| Oil / Water / Air Leakage       |                   |                                     |                                 |
| Lift cylinder (Left)            | No                | Oil Leak: Tilt Cylinder             | No                              |
| Oil Leak: Tilt Cylinder (Left)  | No                | (Right) Oil Leak: Steering Cylinder | No                              |
| Oil Leak: Engine                | No                | Transmission / Torque Converter     | No                              |
| Engine                          | Normal            | Exhaust Gas Color                   | Normal                          |
| Traveling                       | Normal            | Transmission / Torque<br>Converter  | Normal                          |
| Steering                        | Normal            | Break                               | Normal                          |
| Side Break                      | Normal            | Front Attachment                    | Normal                          |
| Wear: Fork                      | Slight            |                                     |                                 |
| Front & Pins                    |                   |                                     |                                 |
| Leak: Cooling Pipes             | No                | Oil Leak: Fuel System               | No                              |
| Overall Rating                  |                   |                                     |                                 |
| Appearance Evaluation           | Fair              | Rust / Corrosion                    | Moderate / within Service Limit |
| Overall Rating                  | Fair              |                                     |                                 |