

# 1900 Bomag BW115AD Roller

Basic information			
Model	BW115AD	Serial No.	227939
Product category	Roller	Manufacturer	Bomag
Year of manufacture	1900	Working hours	
Engine No.			
Detail Information			
Power Transmission System	HST	Drive System	All Wheel Drive
Appearance			
Main Frame	Rusted / Corroded		
Interior			
Seat	Torn	Console	Good Condition
Operation			
Wear / Scratches: Tire (Front Iron-Wheel)	Moderate / within Service Limit	Wear / Scratches: Tire (Rear Iron-Wheel)	Moderate / within Service Limit
Wear / Broken: brush (Front wheel)	Moderate / within Service Limit	Wear / Broken: brush (Rear wheel)	Moderate / within Service Limit
Oil Leak: Travel Device	No	Oil Leak: Travel Pipes	No
Vibration motor pipes	No	Broken / Crack: Vibration motor vibration-proof rubber	Exist
Oil / Water / Air Leakage			
Oil Leak: Steering Cylinder	No	Oil Leak: Engine	No
Pump Device	Slight Film	Transmission / Torque Converter	No
Engine	Normal	Exhaust Gas Color	Normal
Traveling	Normal	Transmission / Torque Converter	Normal
Clutch	Normal	Vibrating device	Normal
Break	Normal	Side Break	Normal
Wear: Center Pins	Moderate / within Service Limit		
Undercarriage / Chassis / Tires			
Oil Leak: Oil Cooler	No	Leak: Radiator	No
Leak: Cooling Pipes	No	Oil Leak: Fuel System	No
Oil Leak: Control Valve	No	Oil Leak: Low Pressure Pipes	No
Oil Leak: High Pressure Pipes	No	Oil Leak: Pilot Pipes	No
Overall Rating			
Appearance Evaluation	Repainted	Rust / Corrosion	Moderate / within Service Limit
Overall Rating	Fair		