

2011 Yanmar VIO70-3A Mini Excavator

Basic information			
Model	VIO70-3A	Serial No.	36045B
Product category	Mini Excavator	Manufacturer	Yanmar
Year of manufacture	2011	Working hours	
Engine No.			
Detail Information			
Job Status	Rental	Cabin / Canopy	Cabin
Cabin Type	Standard	Front Attachment	Backhoe
Type of Shoe	Grouser with Pad	Bucket Attachment	Standard
Other	EPA, Air Conditioner, Arm Crane		
Appearance			
Engine Cover	Rusted / Corroded	Side Covers	Rusted / Corroded
Under Covers	Good Condition	Counter Weight	Scratched
Main Frame	Good Condition	Track Frame	Rusted / Corroded
Cabin	Rusted / Corroded	Door	Good Condition
Interior			
Cabin Interior	Good Condition	Seat	Good Condition
Console	Good Condition	Air Conditioner	Good
Operation			
Engine	Normal	Exhaust Gas Color	Normal
Swing	Normal	Wear: Swing Bearing	Moderate / within Service Limit
Traveling	Normal	Front Attachment	Normal
Front & Pins			
Boom	Normal	Arm	Normal
Wear: Boom Foot Pin	Moderate / within Service Limit	Wear: Boom / Arm Joint Pin	Moderate / within Service Limit
Wear: Arm Tip Pin	Moderate / within Service Limit	Wear: Other Pins	Moderate / within Service Limit
Wear / Deformation: Bucket	Deformation: Moderate	Wear / Deformation: Blade	Wear: Moderate / within Service Limit
Undercarriage / Chassis / Tires			
Seize: Track Links	No	Wear: Track Link Stretching (Right)	Slight
Wear: Track Link Stretching (Left)	Slight	Wear: Track Link Tread (Right)	Moderate / within Service Limit
Wear: Track Link Tread (Left)	Moderate / within Service Limit	Wear: Track Link Pins & Bushings (Right)	Moderate / within Service Limit
Wear: Track Link Pins & Bushings (Left)	Moderate / within Service Limit	Wear: Track Shoe / Rubber Shoe	Slight
Bent / Broken / Missing: Track Shoe	No	Wear: Rubber Pad	Moderate / within Service Limit
Broken / Missing: Rubber Pad	Broken / Missing (Left)	Missing: Rubber Pad	More than 10 Pieces
Wear: Upper Rollers	Moderate / within Service Limit	Wear: Lower Rollers	Moderate / within Service Limit
Oil Leak: Rollers	None	Broken / Missing: Rollers	None
Wear: Front Idler (Right)	Moderate / within Service Limit	Wear: Front Idler (Left)	Moderate / within Service Limit
Wear: Sprocket (Right)	Moderate / within Service Limit	Wear: Sprocket (Left)	Moderate / within Service Limit
Oil Leak: Travel Device	None	Oil Leak: Travel Pipes	None
Oil / Water / Air Leakage			
Oil Leak: Front Pipes	None	Oil Leak: Boom Cylinder	Slight Film
Oil Leak: Arm Cylinder	None	Oil Leak: Bucket Cylinder	None
Oil Leak: Swing Cylinder	None	Oil Leak: Blade Cylinder	None
Oil Leak: Engine	None	Oil Leak: Oil Cooler	None

Leak: Radiator	None	Leak: Cooling Pipes	None
Oil Leak: Fuel System	None	Oil Leak: Upper Structure	None
Oil Leak: Under Carriage	None	Oil Leak: Pilot Pipes	None
Oil Leak: Pilot Valve	None		
Overall Rating			
Appearance Evaluation	Fair	Rust / Corrosion	Moderate / within Service Limit
Overall Rating	Fair		