

2008 Hitachi ZX240LC-3 Hydraulic Excavator

| Basic information | | | |
|---|---------------------|--|----------------|
| Model | ZX240LC-3 | Serial No. | 24588 |
| Product category | Hydraulic Excavator | Manufacturer | Hitachi |
| Year of manufacture | 2008 | Working hours | |
| Engine No. | | | |
| Detail Information | | | |
| Job Status | Demolition | Cabin / Canopy | Cabin |
| Cabin Type | Lift | Front Attachment | High Lift |
| Bucket Attachment | Fork | Other | Piping, EPA |
| Appearance | | | |
| Engine Cover | Good Condition | Side Covers | Good Condition |
| Under Covers | Good Condition | Counter Weight | Good Condition |
| Main Frame | Good Condition | D Frame | Good Condition |
| Track Frame | Good Condition | Cabin | Good Condition |
| Door | Good Condition | | |
| Interior | | | |
| Cabin Interior | Good Condition | Seat | Good Condition |
| Console | Good Condition | Air Conditioner | Good |
| Operation | | | |
| Engine | Normal | Exhaust Gas Color | Normal |
| Swing | Normal | Wear: Swing Bearing | Slight |
| Traveling | Normal | Front Attachment | Normal |
| Pump Device | Normal | | |
| Front & Pins | | | |
| Boom | Normal | Arm | Normal |
| Wear: Boom Foot Pin | Slight | Wear: Boom / Arm Joint Pin | Slight |
| Wear: Arm Tip Pin | Slight | Wear: Other Pins | Slight |
| Wear / Deformation: Bucket | Good | | |
| Undercarriage / Chassis / Tires | | | |
| Seize: Track Links | No | Wear: Track Link Stretching (Right) | Slight |
| Wear: Track Link Stretching (Left) | Slight | Wear: Track Link Tread (Right) | Slight |
| Wear: Track Link Tread (Left) | Slight | Wear: Track Link Pins & Bushings (Right) | Slight |
| Wear: Track Link Pins & Bushings (Left) | Slight | Wear: Track Shoe / Rubber Shoe | Slight |
| Wear: Upper Rollers | Slight | Wear: Lower Rollers | Slight |
| Oil Leak: Rollers | None | Broken / Missing: Rollers | None |
| Wear: Front Idler (Right) | Slight | Wear: Front Idler (Left) | Slight |
| Wear: Sprocket (Right) | Slight | Wear: Sprocket (Left) | Slight |
| Oil Leak: Travel Device | None | Oil Leak: Travel Pipes | None |
| Oil / Water / Air Leakage | | | |
| Oil Leak: Front Pipes | None | Oil Leak: Boom Cylinder (Right) | None |
| Oil Leak: Boom Cylinder (Left) | None | Oil Leak: Arm Cylinder (Right) | None |
| Oil Leak: Bucket Cylinder (Right) | None | Oil Leak: Engine | None |
| Oil Leak: Oil Cooler | None | Leak: Radiator | None |
| Leak: Cooling Pipes | None | Oil Leak: Fuel System | None |

| | | | |
|-------------------------------|------|------------------------------|--------|
| Oil Leak: Control Valve | None | Oil Leak: Low Pressure Pipes | None |
| Oil Leak: High Pressure Pipes | None | Oil Leak: Pilot Pipes | None |
| Oil Leak: Pilot Valve | None | Oil Leak: Center Joint | None |
| Oil Leak: Swing Device | None | Oil Leak: Pump Device | None |
| Overall Rating | | | |
| Appearance Evaluation | Fair | Rust / Corrosion | Slight |
| Overall Rating | Fair | | |