

2002 Hitachi ZX55UR Mini Excavator

Basic information			
Model	ZX55UR	Serial No.	10209
Product category	Mini Excavator	Manufacturer	Hitachi
Year of manufacture	2002	Working hours	
Engine No.			
Detail Information			
Job Status	Civil Engineering	Cabin / Canopy	Cabin
Cabin Type	Standard	Front Attachment	Offset
Type of Shoe	Rubber	Bucket Attachment	Standard
Other	Air Conditioner		
Appearance			
Engine Cover	Rusted / Corroded	Side Covers	Rusted / Corroded
Under Covers	Rusted / Corroded	Counter Weight	Rusted / Corroded
Main Frame	Rusted / Corroded	Track Frame	Rusted / Corroded
Cabin	Rusted / Corroded	Door	Good Condition
Interior			
Cabin Interior	Torn	Seat	Torn
Console	Faded	Air Conditioner	Malfunction
Operation			
Engine	Normal	Exhaust Gas Color	Normal
Swing	Normal	Wear: Swing Bearing	Moderate / within Service Limit
Traveling	Normal	Front Attachment	Normal
Front & Pins			
Boom	Normal	Arm	Deformed / Dent
Wear: Boom Foot Pin	Heavy	Wear: Boom / Arm Joint Pin	Heavy
Wear: Arm Tip Pin	Heavy	Wear: Other Pins	Heavy
Wear / Deformation: Bucket	Wear: Moderate / within Service Limit	Wear / Deformation: Blade	Deformation: Moderate
Undercarriage / Chassis / Tires			
Seize: Track Links	No	Wear: Track Link Stretching (Right)	Slight
Wear: Track Link Stretching (Left)	Slight	Wear: Track Link Tread (Right)	Moderate / within Service Limit
Wear: Track Link Tread (Left)	Moderate / within Service Limit	Wear: Track Shoe / Rubber Shoe	Moderate / within Service Limit
Broken / Crack: Rubber Shoe (Right)	Some Tears	Broken / Crack: Rubber Shoe (Left)	Some Tears
Missing: Rubber Shoe Core	No	Wear: Upper Rollers	Moderate / within Service Limit
Wear: Lower Rollers	Moderate / within Service Limit	Oil Leak: Rollers	None
Broken / Missing: Rollers	None	Wear: Front Idler (Right)	Moderate / within Service Limit
Wear: Front Idler (Left)	Moderate / within Service Limit	Wear: Sprocket (Right)	Moderate / within Service Limit
Wear: Sprocket (Left)	Moderate / within Service Limit	Oil Leak: Travel Device	None
Oil Leak: Travel Pipes	None		
Oil / Water / Air Leakage			
Oil Leak: Front Pipes	None	Oil Leak: Boom Cylinder	None
Oil Leak: Arm Cylinder	None	Oil Leak: Bucket Cylinder	None
Oil Leak: Offset Cylinder	None	Oil Leak: Blade Cylinder	None
Oil Leak: Engine	Slight Film	Oil Leak: Oil Cooler	None
Leak: Radiator	None	Leak: Cooling Pipes	None
Oil Leak: Fuel System	None	Oil Leak: Upper Structure	None
Oil Leak: Under Carriage	None	Oil Leak: Pilot Pipes	Slight Film

Oil Leak: Pilot Valve	Slight Film	Oil Leak: Pump Device	None
Overall Rating			
Appearance Evaluation	Poor	Rust / Corrosion	Heavy
Overall Rating	Usable		