

2011 IHI IC100-2 Carrier

Basic information			
Model	IC100-2	Serial No.	CB001087
Product category	Carrier	Manufacturer	IHI
Year of manufacture	2011	Working hours	
Engine No.			
Detail Information			
Type of Shoe	Rubber	Loading platform type	Gravel carrier
Other	Air Conditioner	Main Frame	Good Condition
Appearance			
Track Frame	Deformed / Dent	Front bumper	Good Condition
Cabin / Canopy	Good Condition	Door	Good Condition
Cabin Interior	Good Condition		
Interior			
Seat	Torn	Console	Good Condition
Air Conditioner	Good Condition		
Undercarriage / Chassis / Tires			
Wear: Rubber Shoe	Moderate / within Service Limit	Wear: Pivot shaft	No
Broken / Missing: Rollers	No	Wear: Front Idler (Right)	Moderate / within Service Limit
Wear: Front Idler (Left)	Moderate / within Service Limit	Wear: Sprocket (Right)	Moderate / within Service Limit
Wear: Sprocket (Left)	Moderate / within Service Limit	Oil Leak: Travel Device	No
Oil Leak: Travel Pipes	No	Oil Leak: Oil Cooler	No
Leak: Radiator	No	Leak: Cooling Pipes	No
Oil Leak: Fuel System	No	Oil Leak: Control Valve	No
Oil Leak: Low Pressure Pipes	No		
Operation			
Broken / Crack: Rubber Shoe (Right)	Slight	Broken / Crack: Rubber Shoe (Left)	Moderate / within Service Limit
Missing: Rubber Shoe Core	No	Wear: Upper Rollers	Moderate / within Service Limit
Wear: Lower Rollers	Moderate / within Service Limit	Oil Leak: Rollers	1 - 4 Pieces
Oil / Water / Air Leakage			
Oil Leak: High Pressure Pipes	No	Pump Device	No
Oil Leak: Pilot Pipes	No	Engine	Normal
Exhaust Gas Color	Normal	Traveling	Normal
Dump cylinder (Right)	Slight Film	Break	Normal
Dump cylinder (Left)	No	Side Break	Normal
Oil Leak: Engine	No	Dumping	Normal
Other working device	Normal		
?? ? ??			
Vessel	Deformation: Moderate	Frame	Normal
Overall Rating			
Appearance Evaluation	Fair	Rust / Corrosion	Moderate / within Service Limit
Overall Rating	Fair		