

2005 Kubota U-30-3S Mini Excavator

Basic information			
Model	U-30-3S	Serial No.	61027
Product category	Mini Excavator	Manufacturer	Kubota
Year of manufacture	2005	Working hours	
Engine No.			
Detail Information			
Job Status	Rental	Cabin / Canopy	Canopy
Cabin Type	Standard	Type of Shoe	Grouser with Pad
Bucket Attachment	Standard	Other	Piping, Multi Lever
Appearance			
Engine Cover	Good Condition	Side Covers	Good Condition
Under Covers	Good Condition	Counter Weight	Rusted / Corroded
Main Frame	Rusted / Corroded	Track Frame	Rusted / Corroded
Cabin	Good Condition		
Interior			
Seat	Torn	Console	Faded
Operation			
Engine	Normal	Exhaust Gas Color	Normal
Swing	Normal	Wear: Swing Bearing	Slight
Traveling	Normal	Front Attachment	Normal
Front & Pins			
Boom	Normal	Arm	Normal
Wear: Boom / Arm Joint Pin	Slight	Wear: Arm Tip Pin	Moderate / within Service Limit
Wear: Other Pins	Slight	Wear / Deformation: Bucket	Wear: Moderate / within Service Limit
Wear / Deformation: Blade	Wear: Moderate / within Service Limit		
Undercarriage / Chassis / Tires			
Seize: Track Links	No	Wear: Track Link Stretching (Right)	Moderate
Wear: Track Link Stretching (Left)	Moderate	Wear: Track Link Tread (Right)	Slight
Wear: Track Link Tread (Left)	Slight	Wear: Track Link Pins & Bushings (Right)	Slight
Wear: Track Link Pins & Bushings (Left)	Slight	Wear: Track Shoe / Rubber Shoe	Slight
Bent / Broken / Missing: Track Shoe	No	Wear: Rubber Pad	Excessive / Required to replace
Broken / Missing: Rubber Pad	Broken / Missing (Left)	Missing: Rubber Pad	More than 10 Pieces
Wear: Upper Rollers	Slight	Wear: Lower Rollers	Slight
Oil Leak: Rollers	1 - 4 Pieces	Broken / Missing: Rollers	None
Wear: Front Idler (Right)	Slight	Wear: Front Idler (Left)	Slight
Wear: Sprocket (Right)	Slight	Wear: Sprocket (Left)	Slight
Oil Leak: Travel Device	None	Oil Leak: Travel Pipes	None
Oil / Water / Air Leakage			
Oil Leak: Front Pipes	Moderate Oozing	Oil Leak: Boom Cylinder	None
Oil Leak: Arm Cylinder	None	Oil Leak: Bucket Cylinder	None
Oil Leak: Swing Cylinder	None	Oil Leak: Blade Cylinder	None
Oil Leak: Engine	None	Oil Leak: Oil Cooler	None
Leak: Radiator	None	Leak: Cooling Pipes	None
Oil Leak: Fuel System	None	Oil Leak: Upper Structure	None

Oil Leak: Under Carriage	None	Oil Leak: Pilot Pipes	None
Oil Leak: Pilot Valve	None	Oil Leak: Pump Device	None
Overall Rating			
Appearance Evaluation	Fair	Rust / Corrosion	Slight
Overall Rating	Fair		