

2006 Yanmar B6-6 Mini Excavator

| Basic information | | | |
|---|---------------------------------------|--|---------------------------------------|
| Model | B6-6 | Serial No. | 60821B |
| Product category | Mini Excavator | Manufacturer | Yanmar |
| Year of manufacture | 2006 | Working hours | |
| Engine No. | | | |
| Detail Information | | | |
| Job Status | Rental | Cabin / Canopy | Canopy |
| Cabin Type | ROPS | Front Attachment | Offset, Standard |
| Type of Shoe | Grouser with Pad | Bucket Attachment | Standard |
| Other | Multi Lever | | |
| Appearance | | | |
| Engine Cover | Good Condition | Side Covers | Rusted / Corroded |
| Under Covers | Rusted / Corroded | Counter Weight | Scratched |
| Main Frame | Good Condition | Track Frame | Rusted / Corroded |
| Cabin | Rusted / Corroded | | |
| Interior | | | |
| Seat | Dirty | Console | Faded |
| Operation | | | |
| Engine | Normal | Exhaust Gas Color | Normal |
| Swing | Normal | Wear: Swing Bearing | Slight |
| Traveling | Normal | Front Attachment | Normal |
| Front & Pins | | | |
| Boom | Normal | Arm | Normal |
| Wear: Boom Foot Pin | Slight | Wear: Boom / Arm Joint Pin | Slight |
| Wear: Arm Tip Pin | Slight | Wear: Other Pins | Slight |
| Wear / Deformation: Bucket | Wear: Moderate / within Service Limit | Wear / Deformation: Blade | Wear: Moderate / within Service Limit |
| Undercarriage / Chassis / Tires | | | |
| Seize: Track Links | No | Wear: Track Link Stretching (Right) | Slight |
| Wear: Track Link Stretching (Left) | Slight | Wear: Track Link Tread (Right) | Slight |
| Wear: Track Link Tread (Left) | Slight | Wear: Track Link Pins & Bushings (Right) | Slight |
| Wear: Track Link Pins & Bushings (Left) | Slight | Wear: Track Shoe / Rubber Shoe | Slight |
| Bent / Broken / Missing: Track Shoe | No | Wear: Rubber Pad | Excessive / Required to replace |
| Broken / Missing: Rubber Pad | Broken / Missing (Left) | Missing: Rubber Pad | More than 10 Pieces |
| Wear: Upper Rollers | Slight | Wear: Lower Rollers | Slight |
| Oil Leak: Rollers | 1 - 4 Pieces | Broken / Missing: Rollers | None |
| Wear: Front Idler (Right) | Slight | Wear: Front Idler (Left) | Slight |
| Wear: Sprocket (Right) | Slight | Wear: Sprocket (Left) | Slight |
| Oil Leak: Travel Device | None | Oil Leak: Travel Pipes | None |
| Oil / Water / Air Leakage | | | |
| Oil Leak: Front Pipes | None | Oil Leak: Boom Cylinder | None |
| Oil Leak: Arm Cylinder | None | Oil Leak: Bucket Cylinder | None |
| Oil Leak: Offset Cylinder | None | Oil Leak: Blade Cylinder | None |
| Oil Leak: Engine | None | Oil Leak: Oil Cooler | None |
| Leak: Radiator | None | Leak: Cooling Pipes | None |

| | | | |
|--------------------------|------|---------------------------|--------|
| Oil Leak: Fuel System | None | Oil Leak: Upper Structure | None |
| Oil Leak: Under Carriage | None | Oil Leak: Pilot Pipes | None |
| Oil Leak: Pilot Valve | None | Oil Leak: Pump Device | None |
| Overall Rating | | | |
| Appearance Evaluation | Good | Rust / Corrosion | Slight |
| Overall Rating | Good | | |