

# 1993 Dynapac CP201WT Roller

Basic information			
Model	CP201WT	Serial No.	40708
Product category	Roller	Manufacturer	Dynapac
Year of manufacture	1993	Working hours	
Engine No.			
Detail Information			
Power Transmission System	HST	Drive System	All Wheel Drive
Documents	Unknown		
Appearance			
Main Frame	Rusted / Corroded	Canopy	Rusted / Corroded
Interior			
Seat	Dirty	Console	Faded
Operation			
Wear / Scratches: Tire (Front Wheel)	Moderate / within Service Limit	Wear / Scratches: Tire (Rear Wheel)	Moderate / within Service Limit
Wear / Scratches: Tire (Front Iron-Wheel)	Moderate / within Service Limit	Wear / Scratches: Tire (Rear Iron-Wheel)	Moderate / within Service Limit
Oil / Water / Air Leakage			
Oil Leak: Steering Cylinder	No	Oil Leak: Engine	No
Engine	Normal	Exhaust Gas Color	Normal
Traveling	Normal	Break	Normal
Side Break	Normal		
Undercarriage / Chassis / Tires			
Oil Leak: Oil Cooler	No	Leak: Radiator	No
Leak: Cooling Pipes	No	Oil Leak: Fuel System	Slight Film
Oil Leak: Low Pressure Pipes	No	Oil Leak: High Pressure Pipes	No
Overall Rating			
Appearance Evaluation	Poor	Rust / Corrosion	Heavy
Overall Rating	Usable		