

# 1991 Others FL80-2 Wheel Loader

Basic information			
Model	FL80-2	Serial No.	1348
Product category	Wheel Loader	Manufacturer	Others
Year of manufacture	1991	Working hours	
Engine No.			
Detail Information			
Type of Tire	Normal	Cabin / Canopy	Cabin
Cabin Type	Standard	Power Transmission System	HST
Drive System	All Wheel Drive	Bucket Attachment	Loading BK
Other	Heater		
Appearance			
Main Frame	Good Condition	Front Frame	Good Condition
Counter Weight	Good Condition	Cabin	Good Condition
Door	Good Condition		
Interior			
Cabin Interior	Good Condition	Seat	Torn
Console	Faded		
Operation			
Engine	Normal	Exhaust Gas Color	Normal
Traveling	Normal	Transmission / Torque Converter	Normal
HST Motor	Normal	Front Attachment	Normal
Pump Device	Normal	Steering	Normal
Break	Normal	Side Break	Normal
Front & Pins			
Lift(Push)Arm	Normal	Bellcrank	Normal
Wear: Front Pins & Bushings	Slight	Wear: Bucket Pins & Bushings	Slight
Wear: Center Pins	Slight	Wear: Bucket Side Plate	Slight
Wear: Bucket Lip	Moderate / within Service Limit	Wear: Bucket Bottom Plate	Moderate / within Service Limit
Wear: Tooth / Cutting Edges	Moderate / within Service Limit		
Undercarriage / Chassis / Tires			
Scratches: Tire (Front-Right Wheel)	Slight	Wear: Tire (Front-Right wheel)	Moderate / within Service Limit
Scratches: Tire (Front-Left Wheel)	Slight	Wear: Tire (Front-Left Wheel)	Moderate / within Service Limit
Scratches: Tire (Rear-Right Wheel)	Slight	Wear: Tire (Rear-Right Wheel)	Slight
Scratches: Tire (Rear-Left Wheel)	Slight	Wear: Tire (Rear-Left Wheel)	Slight
Oil Leak: Axle	No	Oil Leak: Differential Gear Case	No
Oil / Water / Air Leakage			
Oil Leak: Front Pipes	None	Oil Leak: Lift Cylinder (Right)	None
Oil Leak: Lift Cylinder (Left)	None	Oil Leak: Bucket Cylinder	None
Oil Leak: Steering Cylinder	None	Oil Leak: Engine	None
Oil Leak: Oil Cooler	None	Leak: Radiator	None
Leak: Cooling Pipes	None	Oil Leak: Fuel System	None

Compressor	Normal	Oil Leak: Control Valve	None
Oil Leak: Low Pressure Pipes	None	Oil Leak: High Pressure Pipes	None
Oil Leak: Pilot Pipes	None	Oil Leak: Pilot Valve	None
Oil Leak: Pump Device	None	Oil Leak: Transmission / Torcon	None
Overall Rating			
Appearance Evaluation	Fair	Rust / Corrosion	Moderate / within Service Limit
Overall Rating	Fair		