

2006 Komatsu PC30UU-3 Mini Excavator

Basic information			
Model	PC30UU-3	Serial No.	13978
Product category	Mini Excavator	Manufacturer	Komatsu
Year of manufacture	2006	Working hours	
Engine No.			
Detail Information			
Job Status	Civil Engineering	Cabin / Canopy	Canopy
Cabin Type	Standard	Front Attachment	Standard
Type of Shoe	Grouser with Pad	Bucket Attachment	Standard
Other	Arm Crane		
Appearance			
Engine Cover	Good Condition	Side Covers	Deformed / Dent
Under Covers	Good Condition	Counter Weight	Rusted / Corroded
Main Frame	Rusted / Corroded	Track Frame	Rusted / Corroded
Cabin	Good Condition		
Interior			
Cabin Interior	Torn	Seat	Dirty
Console	Good Condition		
Operation			
Engine	Normal	Exhaust Gas Color	Normal
Swing	Normal	Wear: Swing Bearing	Slight
Traveling	Normal	Front Attachment	Normal
Front & Pins			
Boom	Normal	Arm	Normal
Wear: Boom Foot Pin	Moderate / within Service Limit	Wear: Boom / Arm Joint Pin	Moderate / within Service Limit
Wear: Arm Tip Pin	Moderate / within Service Limit	Wear: Other Pins	Moderate / within Service Limit
Wear / Deformation: Bucket	Wear: Moderate / within Service Limit	Wear / Deformation: Blade	Deformation: Moderate
Undercarriage / Chassis / Tires			
Seize: Track Links	No	Wear: Track Link Stretching (Right)	Moderate
Wear: Track Link Stretching (Left)	Moderate	Wear: Track Link Tread (Right)	Moderate / within Service Limit
Wear: Track Link Tread (Left)	Moderate / within Service Limit	Wear: Track Link Pins & Bushings (Right)	Moderate / within Service Limit
Wear: Track Link Pins & Bushings (Left)	Moderate / within Service Limit	Wear: Track Shoe / Rubber Shoe	Moderate / within Service Limit
Bent / Broken / Missing: Track Shoe	No	Wear: Rubber Pad	Moderate / within Service Limit
Broken / Missing: Rubber Pad	No	Missing: Rubber Pad	1 - 4 Pieces
Wear: Upper Rollers	Moderate / within Service Limit	Wear: Lower Rollers	Moderate / within Service Limit
Oil Leak: Rollers	None	Broken / Missing: Rollers	None
Wear: Front Idler (Right)	Moderate / within Service Limit	Wear: Front Idler (Left)	Moderate / within Service Limit
Wear: Sprocket (Right)	Moderate / within Service Limit	Wear: Sprocket (Left)	Moderate / within Service Limit
Oil Leak: Travel Device	None	Oil Leak: Travel Pipes	Slight Film
Oil / Water / Air Leakage			
Oil Leak: Front Pipes	Slight Film	Oil Leak: Boom Cylinder	None
Oil Leak: Arm Cylinder	Moderate Oozing	Oil Leak: Bucket Cylinder	Slight Film
Oil Leak: Offset Cylinder	None	Oil Leak: Blade Cylinder	None
Oil Leak: Engine	Slight Film	Oil Leak: Oil Cooler	Slight Film

Leak: Radiator	None	Leak: Cooling Pipes	None
Oil Leak: Fuel System	None	Oil Leak: Upper Structure	Slight Film
Oil Leak: Under Carriage	None	Oil Leak: Pilot Pipes	None
Oil Leak: Pilot Valve	None	Oil Leak: Pump Device	None
Overall Rating			
Appearance Evaluation	Fair	Rust / Corrosion	Slight
Overall Rating	Fair		