1900 Komatsu PC50UU-2 Mini Excavator

Basic information			
Model	PC50UU-2	Serial No.	9553
Product category	Mini Excavator	Manufacturer	Komatsu
Year of manufacture	1900	Working hours	
Engine No.			
Detail Information			
Job Status	Civil Engineering	Cabin / Canopy	Cabin
Cabin Type	Standard	Front Attachment	Standard
Type of Shoe	Rubber	Bucket Attachment	Standard
Appearance			***************************************
Engine Cover	Rusted / Corroded	Side Covers	Rusted / Corroded
Under Covers	Rusted / Corroded	Counter Weight	Deformed / Dent
Main Frame	Rusted / Corroded	Track Frame	Rusted / Corroded
Cabin	Rusted / Corroded	Door	Not Closed Properly
Interior			11.7
	Damagad	Coat	Torn
Cabin Interior Console	Damaged Faded	Seat	Torn
	ı autu		
Operation			
Engine	Normal	Exhaust Gas Color	Normal
Swing	Normal	Wear: Swing Bearing	Slight
Traveling	Normal	Front Attachment	Normal
Front & Pins			
Boom	Normal	Arm	Normal
Wear: Boom Foot Pin	Slight	Wear: Boom / Arm Joint Pin	
Wear: Arm Tip Pin	Slight	Wear: Other Pins	Slight
Wear / Deformation: Bucke	et Wear: Moderate / within Service Lir	mit Wear / Deformation: Blade	Deformation: Heavy
Undercarriage / Chassis	/ Tires		
Bent / Broken / Missing: Track Shoe	No	Broken / Crack: Rubber Shoe (Right)	No
Broken / Crack: Rubber Shoe (Left)	No	Missing: Rubber Shoe Core	No
Wear: Upper Rollers	Excessive / Required to replace	Oil Leak: Rollers	None
Broken / Missing: Rollers	1 - 4 Pieces	Wear: Front Idler (Right)	Slight
Wear: Front Idler (Left)	Slight	Wear: Sprocket (Right)	Slight
Wear: Sprocket (Left)	Slight	Oil Leak: Travel Device	None
Oil Leak: Travel Pipes	None		
Oil / Water / Air Leakage			
Oil Leak: Front Pipes	None	Oil Leak: Boom Cylinder	None
on Leak. I folk ripes		Oil Leak: Bucket Cylinder	None
	None	Oli Leak. Bucket Cyllilder	
Oil Leak: Arm Cylinder	None None	Oil Leak: Blade Cylinder	None
Oil Leak: Arm Cylinder Oil Leak: Offset Cylinder			
Oil Leak: Arm Cylinder Oil Leak: Offset Cylinder Oil Leak: Engine	None	Oil Leak: Blade Cylinder	None
Oil Leak: Arm Cylinder Oil Leak: Offset Cylinder Oil Leak: Engine Leak: Radiator	None None	Oil Leak: Blade Cylinder Oil Leak: Oil Cooler	None None
Oil Leak: Front Fipes Oil Leak: Arm Cylinder Oil Leak: Offset Cylinder Oil Leak: Engine Leak: Radiator Oil Leak: Fuel System Oil Leak: Under Carriage	None None None	Oil Leak: Blade Cylinder Oil Leak: Oil Cooler Leak: Cooling Pipes	None None
Oil Leak: Arm Cylinder Oil Leak: Offset Cylinder Oil Leak: Engine Leak: Radiator Oil Leak: Fuel System	None None None None	Oil Leak: Blade Cylinder Oil Leak: Oil Cooler Leak: Cooling Pipes Oil Leak: Upper Structure	None None None None
Oil Leak: Arm Cylinder Oil Leak: Offset Cylinder Oil Leak: Engine Leak: Radiator Oil Leak: Fuel System Oil Leak: Under Carriage	None None None None	Oil Leak: Blade Cylinder Oil Leak: Oil Cooler Leak: Cooling Pipes Oil Leak: Upper Structure Oil Leak: Pilot Pipes	None None None None
Oil Leak: Arm Cylinder Oil Leak: Offset Cylinder Oil Leak: Engine Leak: Radiator Oil Leak: Fuel System Oil Leak: Under Carriage Oil Leak: Pilot Valve	None None None None	Oil Leak: Blade Cylinder Oil Leak: Oil Cooler Leak: Cooling Pipes Oil Leak: Upper Structure Oil Leak: Pilot Pipes	None None None None