

## 2001 Yanmar B3-3A Mini Excavator

| Basic information                   |                                       |                                     |                                       |
|-------------------------------------|---------------------------------------|-------------------------------------|---------------------------------------|
| Model                               | B3-3A                                 | Serial No.                          | 36537B                                |
| Product category                    | Mini Excavator                        | Manufacturer                        | Yanmar                                |
| Year of manufacture                 | 2001                                  | Working hours                       |                                       |
| Engine No.                          |                                       |                                     |                                       |
| Detail Information                  |                                       |                                     |                                       |
| Job Status                          | Civil Engineering                     | Cabin / Canopy                      | Canopy                                |
| Cabin Type                          | Standard                              | Front Attachment                    | Standard                              |
| Type of Shoe                        | Rubber                                | Bucket Attachment                   | Standard                              |
| Other                               | EPA, Multi Lever                      |                                     |                                       |
| Appearance                          |                                       |                                     |                                       |
| Engine Cover                        | Good Condition                        | Side Covers                         | Deformed / Dent                       |
| Under Covers                        | Good Condition                        | Counter Weight                      | Rusted / Corroded                     |
| Main Frame                          | Rusted / Corroded                     | Track Frame                         | Rusted / Corroded                     |
| Cabin                               | Rusted / Corroded                     |                                     |                                       |
| Interior                            |                                       |                                     |                                       |
| Cabin Interior                      | Good Condition                        | Seat                                | Good Condition                        |
| Console                             | Good Condition                        |                                     |                                       |
| Operation                           |                                       |                                     |                                       |
| Engine                              | Normal                                | Exhaust Gas Color                   | Normal                                |
| Swing                               | Normal                                | Wear: Swing Bearing                 | Slight                                |
| Traveling                           | Normal                                | Front Attachment                    | Normal                                |
| Front & Pins                        |                                       |                                     |                                       |
| Boom                                | Normal                                | Arm                                 | Normal                                |
| Wear: Boom Foot Pin                 | Moderate / within Service Limit       | Wear: Boom / Arm Joint Pin          | Moderate / within Service Limit       |
| Wear: Arm Tip Pin                   | Moderate / within Service Limit       | Wear: Other Pins                    | Moderate / within Service Limit       |
| Wear / Deformation: Bucket          | Wear: Moderate / within Service Limit | Wear / Deformation: Blade           | Wear: Moderate / within Service Limit |
| Undercarriage / Chassis / Tires     |                                       |                                     |                                       |
| Wear: Track Link Stretching (Right) | Moderate                              | Wear: Track Link Stretching (Left)  | Moderate                              |
| Wear: Track Link Tread (Right)      | Moderate / within Service Limit       | Wear: Track Link Tread (Left)       | Moderate / within Service Limit       |
| Wear: Track Shoe / Rubber Shoe      | Moderate / within Service Limit       | Broken / Crack: Rubber Shoe (Right) | Some Tears                            |
| Broken / Crack: Rubber Shoe (Left)  | Some Tears                            | Missing: Rubber Shoe Core           | No                                    |
| Wear: Upper Rollers                 | Moderate / within Service Limit       | Wear: Lower Rollers                 | Moderate / within Service Limit       |
| Oil Leak: Rollers                   | None                                  | Broken / Missing: Rollers           | None                                  |
| Wear: Front Idler (Right)           | Moderate / within Service Limit       | Wear: Front Idler (Left)            | Moderate / within Service Limit       |
| Wear: Sprocket (Right)              | Moderate / within Service Limit       | Wear: Sprocket (Left)               | Moderate / within Service Limit       |
| Oil Leak: Travel Device             | None                                  | Oil Leak: Travel Pipes              | None                                  |
| Oil / Water / Air Leakage           |                                       |                                     |                                       |
| Oil Leak: Front Pipes               | None                                  | Oil Leak: Boom Cylinder             | None                                  |
| Oil Leak: Arm Cylinder              | None                                  | Oil Leak: Bucket Cylinder           | None                                  |
| Oil Leak: Swing Cylinder            | None                                  | Oil Leak: Blade Cylinder            | Slight Film                           |
| Oil Leak: Engine                    | Slight Film                           | Oil Leak: Oil Cooler                | None                                  |
| Leak: Radiator                      | None                                  | Leak: Cooling Pipes                 | None                                  |
| Oil Leak: Fuel System               | None                                  | Oil Leak: Under Carriage            | Slight Film                           |
| Oil Leak: Pilot Pipes               | None                                  | Oil Leak: Pilot Valve               | None                                  |
| Oil Leak: Pump Device               | Slight Film                           |                                     |                                       |

|                       |      |                  |                                 |
|-----------------------|------|------------------|---------------------------------|
| Overall Rating        |      |                  |                                 |
| Appearance Evaluation | Fair | Rust / Corrosion | Moderate / within Service Limit |
| Overall Rating        | Fair |                  |                                 |