

# 1900 IHI IC35 Carrier

|                                     |                |                                    |                     |
|-------------------------------------|----------------|------------------------------------|---------------------|
| Basic information                   |                |                                    |                     |
| Model                               | IC35           | Serial No.                         | 440                 |
| Product category                    | Carrier        | Manufacturer                       | IHI                 |
| Year of manufacture                 | 1900           | Working hours                      |                     |
| Engine No.                          |                |                                    |                     |
| Detail Information                  |                |                                    |                     |
| Type of Shoe                        | Rubber         | Loading platform type              | 3-side tipper truck |
| Main Frame                          | Good Condition |                                    |                     |
| Appearance                          |                |                                    |                     |
| Track Frame                         | Good Condition | Front bumper                       | Good Condition      |
| Cabin / Canopy                      | Good Condition |                                    |                     |
| Interior                            |                |                                    |                     |
| Seat                                | Dirty          | Console                            | Good Condition      |
| Undercarriage / Chassis / Tires     |                |                                    |                     |
| Wear: Rubber Shoe                   | Slight         | Wear: Pivot shaft                  | No                  |
| Broken / Missing: Rollers           | No             | Wear: Front Idler (Right)          | Slight              |
| Wear: Front Idler (Left)            | Slight         | Wear: Sprocket (Right)             | Slight              |
| Wear: Sprocket (Left)               | Slight         | Oil Leak: Travel Device            | No                  |
| Oil Leak: Travel Pipes              | No             | Oil Leak: Oil Cooler               | No                  |
| Leak: Radiator                      | No             | Leak: Cooling Pipes                | No                  |
| Oil Leak: Fuel System               | No             | Oil Leak: Control Valve            | No                  |
| Oil Leak: Low Pressure Pipes        | No             |                                    |                     |
| Operation                           |                |                                    |                     |
| Broken / Crack: Rubber Shoe (Right) | Slight         | Broken / Crack: Rubber Shoe (Left) | Slight              |
| Missing: Rubber Shoe Core           | No             | Wear: Upper Rollers                | Slight              |
| Wear: Lower Rollers                 | Slight         | Oil Leak: Rollers                  | No                  |
| Oil / Water / Air Leakage           |                |                                    |                     |
| Oil Leak: High Pressure Pipes       | No             | Pump Device                        | No                  |
| Oil Leak: Pilot Valve               | No             | Oil Leak: Pilot Pipes              | No                  |
| Engine                              | Normal         | Exhaust Gas Color                  | Normal              |
| Traveling                           | Normal         | Dump cylinder (Right)              | No                  |
| Break                               | Normal         | Side Break                         | Normal              |
| Oil Leak: Engine                    | No             | Dumping                            | Normal              |
| ?? ? ??                             |                |                                    |                     |
| Vessel                              | Normal         | Frame                              | Normal              |
| Overall Rating                      |                |                                    |                     |
| Appearance Evaluation               | Repainted      | Rust / Corrosion                   | No                  |
| Overall Rating                      | Fair           |                                    |                     |