

1998 Hanta CRP-100? Other

Basic information			
Model	CRP-100?	Serial No.	64
Product category	Other	Manufacturer	Hanta
Year of manufacture	1998	Working hours	
Engine No.			
Appearance			
Cover	Deformed / Dent, Rusted / Corroded	Main Frame	Rusted / Corroded
Interior			
Seat	Good Condition	Console	Faded
Undercarriage / Chassis / Tires			
Scratches: Tire	Moderate / within Service Limit	Oil Leak: Oil Cooler	No
Leak: Radiator	No	Leak: Cooling Pipes	No
Oil Leak: Fuel System	No	Oil Leak: Control Valve	No
Oil Leak: Low Pressure Pipes	No	Oil Leak: High Pressure Pipes	No
Oil Leak: Pilot Pipes	No	Oil Leak: Pilot Valve	No
Pump Device	No		
Operation			
Wear: Tire	Moderate / within Service Limit	Oil Leak: Travel Device	No
Oil Leak: Travel Pipes	No		
Oil / Water / Air Leakage			
Oil Leak: Cylinder	No	Oil Leak: Engine	Slight Film
Engine	Normal	Exhaust Gas Color	White Smoke
Traveling	Normal	Pump Device	Normal
Steering	Normal	Break	Normal
Overall Rating			
Appearance Evaluation	Poor	Rust / Corrosion	Moderate / within Service Limit
Overall Rating	Usable		