

1900 Morooka MST-600 Carrier

Basic information			
Model	MST-600	Serial No.	836
Product category	Carrier	Manufacturer	Morooka
Year of manufacture	1900	Working hours	
Engine No.			
Detail Information			
Type of Shoe	Rubber	Loading platform type	Gravel carrier
Main Frame	Rusted / Corroded		
Appearance			
Track Frame	Rusted / Corroded	Front bumper	Rusted / Corroded
Cabin / Canopy	Deformed / Dent, Rusted / Corroded		
Interior			
Seat	Torn	Console	Faded, Malfunction
Wear: Track Link Stretching (Right)	Moderate		
Operation			
Wear: Track Link Stretching (Left)	Moderate	Wear: Track Link Tread (Right)	Moderate / within Service Limit
Wear: Track Link Tread (Left)	Moderate / within Service Limit	Broken / Crack: Rubber Shoe (Right)	Moderate / within Service Limit
Broken / Crack: Rubber Shoe (Left)	Moderate / within Service Limit	Missing: Rubber Shoe Core	No
Wear: Upper Rollers	Moderate / within Service Limit	Wear: Lower Rollers	Moderate / within Service Limit
Oil Leak: Rollers	No		
Undercarriage / Chassis / Tires			
Wear: Rubber Shoe	Moderate / within Service Limit	Wear: Pivot shaft	No
Broken / Missing: Rollers	No	Wear: Front Idler (Right)	Moderate / within Service Limit
Wear: Front Idler (Left)	Moderate / within Service Limit	Wear: Sprocket (Right)	Moderate / within Service Limit
Wear: Sprocket (Left)	Moderate / within Service Limit	Oil Leak: Travel Device	No
Oil Leak: Travel Pipes	No	Oil Leak: Oil Cooler	No
Leak: Radiator	No	Leak: Cooling Pipes	No
Oil Leak: Fuel System	No	Oil Leak: Control Valve	Slight Film
Oil Leak: Low Pressure Pipes	Slight Film		
Oil / Water / Air Leakage			
Oil Leak: High Pressure Pipes	Slight Film	Pump Device	Slight Film
Engine	Lack of Power	Exhaust Gas Color	White Smoke
Traveling	Slow Movement	Break	Normal
Oil Leak: Engine	Slight Film	Dumping	Malfunction
?? ? ??			
Vessel	Deformation: Heavy	Frame	Deformation: Heavy
Overall Rating			
Appearance Evaluation	Poor	Rust / Corrosion	Heavy
Overall Rating	Usable		