

2012 Kawasaki 70ZV-2 Wheel Loader

Basic information			
Model	70ZV-2	Serial No.	70C5-0707
Product category	Wheel Loader	Manufacturer	Kawasaki
Year of manufacture	2012	Working hours	
Engine No.			
Detail Information			
Job Status	Others	Type of Tire	Normal
Cabin / Canopy	Cabin	Cabin Type	ROPS
Power Transmission System	Torque Converter	Drive System	All Wheel Drive
Bucket Attachment	Loading BK	Other	Air Conditioner
Appearance			
Main Frame	Rusted / Corroded	Front Frame	Rusted / Corroded
Counter Weight	Scratched	Cabin	Rusted / Corroded
Door	Good Condition		
Interior			
Cabin Interior	Good Condition	Seat	Good Condition
Console	Good Condition	Air Conditioner	Good
Operation			
Engine	Normal	Exhaust Gas Color	Normal
Traveling	Normal	Transmission / Torque Converter	Normal
Front Attachment	Normal	Pump Device	Normal
Steering	Normal	Break	Normal
Side Break	Normal		
Front & Pins			
Lift(Push)Arm	Normal	Bellcrank	Normal
Wear: Front Pins & Bushings	Slight	Wear: Bucket Pins & Bushings	Slight
Wear: Center Pins	Slight	Wear: Bucket Side Plate	Moderate / within Service Limit
Wear: Bucket Lip	Moderate / within Service Limit	Wear: Bucket Bottom Plate	Moderate / within Service Limit
Wear: Tooth / Cutting Edges	Moderate / within Service Limit		
Undercarriage / Chassis / Tires			
Scratches: Tire (Front-Right Wheel)	Slight	Wear: Tire (Front-Right wheel)	Slight
Scratches: Tire (Front-Left Wheel)	Slight	Wear: Tire (Front-Left Wheel)	Slight
Scratches: Tire (Rear-Right Wheel)	Slight	Wear: Tire (Rear-Right Wheel)	Slight
Scratches: Tire (Rear-Left Wheel)	Slight	Wear: Tire (Rear-Left Wheel)	Slight
Oil Leak: Axle	No	Oil Leak: Differential Gear Case	No
Oil / Water / Air Leakage			
Oil Leak: Front Pipes	None	Oil Leak: Lift Cylinder (Right)	None
Oil Leak: Lift Cylinder (Left)	None	Oil Leak: Bucket Cylinder	None
Oil Leak: Steering Cylinder	None	Oil Leak: Engine	Slight Film
Oil Leak: Oil Cooler	None	Leak: Radiator	None
Leak: Cooling Pipes	None	Oil Leak: Fuel System	Slight Film

Oil Leak: Control Valve	None	Oil Leak: Low Pressure Pipes	None
Oil Leak: High Pressure Pipes	None	Oil Leak: Pilot Pipes	None
Oil Leak: Pilot Valve	None	Oil Leak: Pump Device	None
Overall Rating			
Appearance Evaluation	Poor	Rust / Corrosion	Heavy
Overall Rating	Usable		