## 2012 Kobelco SK35SR-5 Mini Excavator

Basic information			
Model	SK35SR-5	Serial No.	PX15-22457
Product category	Mini Excavator	Manufacturer	Kobelco
Year of manufacture	2012	Working hours	
Engine No.			
Detail Information			
Job Status	Quarry	Cabin / Canopy	Cabin
Cabin Type	ROPS	Front Attachment	Standard
Type of Shoe	Grouser with Pad	Bucket Attachment	Skeleton Bucket
Other	Piping, EPA, Air Conditioner		
Appearance			
Engine Cover	Good Condition	Side Covers	Deformed / Dent
Under Covers	Good Condition	Counter Weight	Rusted / Corroded
Main Frame	Good Condition	Track Frame	Rusted / Corroded
Cabin	Good Condition	Door	Good Condition
Intorior			
Interior Cabin Interior	Good Condition	Seat	Good Condition
Console		Air Conditioner	Good
Console	Good Condition	All Conditioner	G000
Operation			
Engine	Normal	Exhaust Gas Color	Normal
Swing	Normal	Wear: Swing Bearing	Slight
Traveling	Normal	Front Attachment	Normal
Front & Pins			
Boom	Normal	Arm	Normal
Wear: Boom Foot Pin	Slight	Wear: Boom / Arm Joint Pin	Slight
Wear: Arm Tip Pin	Slight	Wear: Other Pins	Slight
Wear / Deformation: Bucket	Wear: Moderate / within Service Limit	Wear / Deformation: Blade	Wear: Moderate / within Service Limit
Undercarriage / Chassis /	Tires		
Seize: Track Links	No	Wear: Track Link Stretching (Right)	Moderate
Wear: Track Link Stretching (Left)	Moderate	Wear: Track Link Tread	Moderate / within Service Limit
		(Right)	Wilderate / Within Colvice Limit
Wear: Track Link Tread (Left)	Moderate / within Service Limit	Wear: Track Link Pins & Bushings (Right)	Moderate / within Service Limit
	Moderate / within Service Limit  Moderate / within Service Limit	Wear: Track Link Pins &	
(Left) Wear: Track Link Pins &		Wear: Track Link Pins & Bushings (Right) Wear: Track Shoe / Rubber	Moderate / within Service Limit
(Left) Wear: Track Link Pins & Bushings (Left) Bent / Broken / Missing:	Moderate / within Service Limit	Wear: Track Link Pins & Bushings (Right) Wear: Track Shoe / Rubber Shoe	Moderate / within Service Limit  Moderate / within Service Limit
(Left) Wear: Track Link Pins & Bushings (Left) Bent / Broken / Missing: Track Shoe Broken / Missing: Rubber	Moderate / within Service Limit No	Wear: Track Link Pins & Bushings (Right) Wear: Track Shoe / Rubber Shoe Wear: Rubber Pad	Moderate / within Service Limit  Moderate / within Service Limit  Moderate / within Service Limit
(Left) Wear: Track Link Pins & Bushings (Left) Bent / Broken / Missing: Track Shoe Broken / Missing: Rubber Pad Wear: Upper Rollers Oil Leak: Rollers	Moderate / within Service Limit No No	Wear: Track Link Pins & Bushings (Right) Wear: Track Shoe / Rubber Shoe Wear: Rubber Pad Missing: Rubber Pad Wear: Lower Rollers Broken / Missing: Rollers	Moderate / within Service Limit  Moderate / within Service Limit  Moderate / within Service Limit  No
(Left) Wear: Track Link Pins & Bushings (Left) Bent / Broken / Missing: Track Shoe Broken / Missing: Rubber Pad Wear: Upper Rollers Oil Leak: Rollers Wear: Front Idler (Right)	Moderate / within Service Limit  No  No  Moderate / within Service Limit  None  Moderate / within Service Limit	Wear: Track Link Pins & Bushings (Right) Wear: Track Shoe / Rubber Shoe Wear: Rubber Pad Missing: Rubber Pad Wear: Lower Rollers Broken / Missing: Rollers Wear: Front Idler (Left)	Moderate / within Service Limit  Moderate / within Service Limit  Moderate / within Service Limit  No  Moderate / within Service Limit  None  Moderate / within Service Limit
(Left) Wear: Track Link Pins & Bushings (Left) Bent / Broken / Missing: Track Shoe Broken / Missing: Rubber Pad Wear: Upper Rollers Oil Leak: Rollers	Moderate / within Service Limit  No  No  Moderate / within Service Limit  None	Wear: Track Link Pins & Bushings (Right) Wear: Track Shoe / Rubber Shoe Wear: Rubber Pad Missing: Rubber Pad Wear: Lower Rollers Broken / Missing: Rollers Wear: Front Idler (Left) Wear: Sprocket (Left)	Moderate / within Service Limit  Moderate / within Service Limit  Moderate / within Service Limit  No  Moderate / within Service Limit  None
(Left) Wear: Track Link Pins & Bushings (Left) Bent / Broken / Missing: Track Shoe Broken / Missing: Rubber Pad Wear: Upper Rollers Oil Leak: Rollers Wear: Front Idler (Right) Wear: Sprocket (Right) Oil Leak: Travel Device	Moderate / within Service Limit  No  No  Moderate / within Service Limit  None  Moderate / within Service Limit  Moderate / within Service Limit	Wear: Track Link Pins & Bushings (Right) Wear: Track Shoe / Rubber Shoe Wear: Rubber Pad Missing: Rubber Pad Wear: Lower Rollers Broken / Missing: Rollers Wear: Front Idler (Left)	Moderate / within Service Limit  Moderate / within Service Limit  Moderate / within Service Limit  No  Moderate / within Service Limit  None  Moderate / within Service Limit  Moderate / within Service Limit  Moderate / within Service Limit
(Left) Wear: Track Link Pins & Bushings (Left) Bent / Broken / Missing: Track Shoe Broken / Missing: Rubber Pad Wear: Upper Rollers Oil Leak: Rollers Wear: Front Idler (Right) Wear: Sprocket (Right) Oil Leak: Travel Device Oil / Water / Air Leakage	Moderate / within Service Limit  No  No  Moderate / within Service Limit  None  Moderate / within Service Limit  Moderate / within Service Limit  Moderate / within Service Limit  None	Wear: Track Link Pins & Bushings (Right) Wear: Track Shoe / Rubber Shoe Wear: Rubber Pad Missing: Rubber Pad Wear: Lower Rollers Broken / Missing: Rollers Wear: Front Idler (Left) Wear: Sprocket (Left) Oil Leak: Travel Pipes	Moderate / within Service Limit  Moderate / within Service Limit  Moderate / within Service Limit  No  Moderate / within Service Limit  None  Moderate / within Service Limit  Moderate / within Service Limit  Moderate / within Service Limit  None
(Left) Wear: Track Link Pins & Bushings (Left) Bent / Broken / Missing: Track Shoe Broken / Missing: Rubber Pad Wear: Upper Rollers Oil Leak: Rollers Wear: Front Idler (Right) Wear: Sprocket (Right) Oil Leak: Travel Device Oil / Water / Air Leakage Oil Leak: Front Pipes	Moderate / within Service Limit  No  No  Moderate / within Service Limit  None  Moderate / within Service Limit  Moderate / within Service Limit  Moderate / within Service Limit  None  None	Wear: Track Link Pins & Bushings (Right) Wear: Track Shoe / Rubber Shoe Wear: Rubber Pad Missing: Rubber Pad Wear: Lower Rollers Broken / Missing: Rollers Wear: Front Idler (Left) Wear: Sprocket (Left) Oil Leak: Travel Pipes Oil Leak: Boom Cylinder	Moderate / within Service Limit  Moderate / within Service Limit  Moderate / within Service Limit  No  Moderate / within Service Limit  None  Moderate / within Service Limit  Moderate / within Service Limit  Moderate / within Service Limit  None  None
(Left) Wear: Track Link Pins & Bushings (Left) Bent / Broken / Missing: Track Shoe Broken / Missing: Rubber Pad Wear: Upper Rollers Oil Leak: Rollers Wear: Front Idler (Right) Wear: Sprocket (Right) Oil Leak: Travel Device Oil / Water / Air Leakage	Moderate / within Service Limit  No  No  Moderate / within Service Limit  None  Moderate / within Service Limit  Moderate / within Service Limit  Moderate / within Service Limit  None	Wear: Track Link Pins & Bushings (Right) Wear: Track Shoe / Rubber Shoe Wear: Rubber Pad Missing: Rubber Pad Wear: Lower Rollers Broken / Missing: Rollers Wear: Front Idler (Left) Wear: Sprocket (Left) Oil Leak: Travel Pipes	Moderate / within Service Limit  Moderate / within Service Limit  Moderate / within Service Limit  No  Moderate / within Service Limit  None  Moderate / within Service Limit  Moderate / within Service Limit  Moderate / within Service Limit  None

Leak: Radiator	None	Leak: Cooling Pipes	None	
Oil Leak: Fuel System	None	Oil Leak: Upper Structure	None	
Oil Leak: Under Carriage	None	Oil Leak: Pilot Pipes	None	
Oil Leak: Pilot Valve	None	Oil Leak: Pump Device	None	
Overall Rating				
Appearance Evaluation	Good	Rust / Corrosion	Slight	
Overall Rating	Good			