

2007 Others SH120-3 Hydraulic Excavator

| Basic information | | | |
|---|---------------------------------------|--|---------------------------------------|
| Model | SH120-3 | Serial No. | 120A3-6896 |
| Product category | Hydraulic Excavator | Manufacturer | Others |
| Year of manufacture | 2007 | Working hours | |
| Engine No. | | | |
| Detail Information | | | |
| Job Status | Civil Engineering | Cabin / Canopy | Cabin |
| Cabin Type | Standard | Front Attachment | Standard |
| Type of Shoe | Grouser with Pad | Bucket Attachment | Standard |
| Other | Piping, Air Conditioner | | |
| Appearance | | | |
| Engine Cover | Rusted / Corroded | Side Covers | Deformed / Dent |
| Under Covers | Deformed / Dent | Counter Weight | Scratched |
| Main Frame | Rusted / Corroded | D Frame | Rusted / Corroded |
| Track Frame | Rusted / Corroded | Cabin | Rusted / Corroded |
| Door | Good Condition | | |
| Interior | | | |
| Cabin Interior | Torn | Seat | Good Condition |
| Console | Good Condition | Air Conditioner | Good |
| Operation | | | |
| Engine | Normal | Exhaust Gas Color | Normal |
| Swing | Normal | Wear: Swing Bearing | Slight |
| Traveling | Normal | Front Attachment | Normal |
| Pump Device | Normal | | |
| Front & Pins | | | |
| Boom | Normal | Arm | Normal |
| Wear: Boom Foot Pin | Moderate / within Service Limit | Wear: Boom / Arm Joint Pin | Moderate / within Service Limit |
| Wear: Arm Tip Pin | Moderate / within Service Limit | Wear: Other Pins | Moderate / within Service Limit |
| Wear / Deformation: Bucket | Wear: Moderate / within Service Limit | Wear / Deformation: Blade | Wear: Moderate / within Service Limit |
| Undercarriage / Chassis / Tires | | | |
| Seize: Track Links | No | Wear: Track Link Stretching (Right) | Moderate |
| Wear: Track Link Stretching (Left) | Moderate | Wear: Track Link Tread (Right) | Moderate / within Service Limit |
| Wear: Track Link Tread (Left) | Moderate / within Service Limit | Wear: Track Link Pins & Bushings (Right) | Moderate / within Service Limit |
| Wear: Track Link Pins & Bushings (Left) | Moderate / within Service Limit | Wear: Track Shoe / Rubber Shoe | Moderate / within Service Limit |
| Bent / Broken / Missing: Track Shoe | No | Wear: Rubber Pad | Moderate / within Service Limit |
| Broken / Missing: Rubber Pad | No | Missing: Rubber Pad | 1 - 4 Pieces |
| Wear: Upper Rollers | Moderate / within Service Limit | Wear: Lower Rollers | Moderate / within Service Limit |
| Oil Leak: Rollers | 1 - 4 Pieces | Broken / Missing: Rollers | None |
| Wear: Front Idler (Right) | Moderate / within Service Limit | Wear: Front Idler (Left) | Moderate / within Service Limit |
| Wear: Sprocket (Right) | Moderate / within Service Limit | Wear: Sprocket (Left) | Moderate / within Service Limit |
| Oil Leak: Travel Device | Slight Film | Oil Leak: Travel Pipes | None |
| Oil / Water / Air Leakage | | | |
| Oil Leak: Front Pipes | None | Oil Leak: Boom Cylinder (Right) | None |

| | | | |
|-----------------------------------|------|--------------------------------|-------------|
| Oil Leak: Boom Cylinder (Left) | None | Oil Leak: Arm Cylinder (Right) | None |
| Oil Leak: Bucket Cylinder (Right) | None | Oil Leak: Engine | None |
| Oil Leak: Oil Cooler | None | Leak: Radiator | Slight Film |
| Leak: Cooling Pipes | None | Oil Leak: Fuel System | None |
| Oil Leak: Control Valve | None | Oil Leak: Low Pressure Pipes | None |
| Oil Leak: High Pressure Pipes | None | Oil Leak: Pilot Pipes | None |
| Oil Leak: Pilot Valve | None | Oil Leak: Center Joint | None |
| Oil Leak: Swing Device | None | Oil Leak: Pump Device | None |
| Overall Rating | | | |
| Appearance Evaluation | Fair | Rust / Corrosion | Slight |
| Overall Rating | Fair | | |