

2007 Others SH120-3 Hydraulic Excavator

Basic information			
Model	SH120-3	Serial No.	120A3-6998
Product category	Hydraulic Excavator	Manufacturer	Others
Year of manufacture	2007	Working hours	
Engine No.			
Detail Information			
Job Status	Civil Engineering	Cabin / Canopy	Cabin
Cabin Type	Standard	Front Attachment	Standard
Type of Shoe	Grouser with Pad	Bucket Attachment	Standard
Other	Air Conditioner, Multi Lever, Arm Crane		
Appearance			
Engine Cover	Good Condition	Side Covers	Good Condition
Under Covers	Deformed / Dent	Counter Weight	Scratched
Main Frame	Rusted / Corroded	D Frame	Rusted / Corroded
Track Frame	Rusted / Corroded	Cabin	Good Condition
Door	Good Condition		
Interior			
Cabin Interior	Good Condition	Seat	Torn
Console	Good Condition	Air Conditioner	Good
Operation			
Engine	Normal	Exhaust Gas Color	Normal
Swing	Normal	Wear: Swing Bearing	Slight
Traveling	Normal	Front Attachment	Normal
Pump Device	Normal		
Front & Pins			
Boom	Normal	Arm	Normal
Wear: Boom Foot Pin	Moderate / within Service Limit	Wear: Boom / Arm Joint Pin	Moderate / within Service Limit
Wear: Arm Tip Pin	Moderate / within Service Limit	Wear: Other Pins	Moderate / within Service Limit
Wear / Deformation: Bucket	Wear: Moderate / within Service Limit	Wear / Deformation: Blade	Wear: Moderate / within Service Limit
Undercarriage / Chassis / Tires			
Seize: Track Links	No	Wear: Track Link Stretching (Right)	Moderate
Wear: Track Link Stretching (Left)	Moderate	Wear: Track Link Tread (Right)	Moderate / within Service Limit
Wear: Track Link Tread (Left)	Moderate / within Service Limit	Wear: Track Link Pins & Bushings (Right)	Moderate / within Service Limit
Wear: Track Link Pins & Bushings (Left)	Moderate / within Service Limit	Wear: Track Shoe / Rubber Shoe	Moderate / within Service Limit
Wear: Upper Rollers	Moderate / within Service Limit	Wear: Lower Rollers	Moderate / within Service Limit
Oil Leak: Rollers	None	Broken / Missing: Rollers	None
Wear: Front Idler (Right)	Moderate / within Service Limit	Wear: Front Idler (Left)	Moderate / within Service Limit
Wear: Sprocket (Right)	Moderate / within Service Limit	Wear: Sprocket (Left)	Moderate / within Service Limit
Oil Leak: Travel Device	None	Oil Leak: Travel Pipes	None
Oil / Water / Air Leakage			
Oil Leak: Front Pipes	None	Oil Leak: Boom Cylinder (Right)	None
Oil Leak: Arm Cylinder (Right)	None	Oil Leak: Bucket Cylinder (Right)	None
Oil Leak: Engine	None	Oil Leak: Oil Cooler	None
Leak: Radiator	None	Leak: Cooling Pipes	None

Oil Leak: Fuel System	None	Oil Leak: Control Valve	None
Oil Leak: Low Pressure Pipes	None	Oil Leak: High Pressure Pipes	None
Oil Leak: Pilot Pipes	None	Oil Leak: Pilot Valve	None
Oil Leak: Center Joint	None	Oil Leak: Swing Device	Slight Film
Oil Leak: Pump Device	None		
Overall Rating			
Appearance Evaluation	Fair	Rust / Corrosion	Slight
Overall Rating	Fair		