

## 2005 Yanmar B6-6 Hydraulic Excavator

| Basic information                  |                                 |                                     |                                 |
|------------------------------------|---------------------------------|-------------------------------------|---------------------------------|
| Model                              | B6-6                            | Serial No.                          | 60541B                          |
| Product category                   | Hydraulic Excavator             | Manufacturer                        | Yanmar                          |
| Year of manufacture                | 2005                            | Working hours                       |                                 |
| Engine No.                         |                                 |                                     |                                 |
| Detail Information                 |                                 |                                     |                                 |
| Job Status                         | Rental                          | Cabin / Canopy                      | Canopy                          |
| Cabin Type                         | Standard                        | Type of Shoe                        | Rubber                          |
| Bucket Attachment                  | Standard                        | Other                               | EPA, Arm Crane                  |
| Appearance                         |                                 |                                     |                                 |
| Engine Cover                       | Good Condition                  | Side Covers                         | Good Condition                  |
| Under Covers                       | Good Condition                  | Counter Weight                      | Good Condition                  |
| Main Frame                         | Good Condition                  | D Frame                             | Good Condition                  |
| Track Frame                        | Good Condition                  |                                     |                                 |
| Interior                           |                                 |                                     |                                 |
| Seat                               | Good Condition                  | Console                             | Good Condition                  |
| Operation                          |                                 |                                     |                                 |
| Engine                             | Normal                          | Exhaust Gas Color                   | Normal                          |
| Swing                              | Normal                          | Wear: Swing Bearing                 | Slight                          |
| Traveling                          | Normal                          | Front Attachment                    | Normal                          |
| Pump Device                        | Normal                          |                                     |                                 |
| Front & Pins                       |                                 |                                     |                                 |
| Boom                               | Normal                          | Arm                                 | Normal                          |
| Wear: Boom Foot Pin                | Slight                          | Wear: Boom / Arm Joint Pin          | Slight                          |
| Wear: Arm Tip Pin                  | Slight                          | Wear: Other Pins                    | Slight                          |
| Wear / Deformation: Bucket         | Good                            | Wear / Deformation: Blade           | Normal                          |
| Undercarriage / Chassis / Tires    |                                 |                                     |                                 |
| Wear: Track Shoe / Rubber Shoe     | Moderate / within Service Limit | Broken / Crack: Rubber Shoe (Right) | Moderate                        |
| Broken / Crack: Rubber Shoe (Left) | No                              | Missing: Rubber Shoe Core           | No                              |
| Wear: Upper Rollers                | Slight                          | Wear: Lower Rollers                 | Slight                          |
| Oil Leak: Rollers                  | None                            | Broken / Missing: Rollers           | None                            |
| Wear: Front Idler (Right)          | Slight                          | Wear: Front Idler (Left)            | Slight                          |
| Wear: Sprocket (Right)             | Moderate / within Service Limit | Wear: Sprocket (Left)               | Moderate / within Service Limit |
| Oil Leak: Travel Device            | None                            | Oil Leak: Travel Pipes              | None                            |
| Oil / Water / Air Leakage          |                                 |                                     |                                 |
| Oil Leak: Front Pipes              | None                            | Oil Leak: Boom Cylinder (Right)     | None                            |
| Oil Leak: Boom Cylinder (Left)     | None                            | Oil Leak: Arm Cylinder (Right)      | None                            |
| Oil Leak: Bucket Cylinder (Right)  | None                            | Oil Leak: Offset Cylinder           | None                            |
| Oil Leak: Blade Cylinder           | None                            | Oil Leak: Engine                    | None                            |
| Oil Leak: Oil Cooler               | None                            | Leak: Radiator                      | None                            |
| Leak: Cooling Pipes                | None                            | Oil Leak: Fuel System               | None                            |
| Oil Leak: Control Valve            | None                            | Oil Leak: Low Pressure Pipes        | None                            |
| Oil Leak: High Pressure Pipes      | None                            | Oil Leak: Pilot Pipes               | None                            |
| Oil Leak: Pilot Valve              | None                            | Oil Leak: Center Joint              | None                            |

|                        |      |                       |                                 |
|------------------------|------|-----------------------|---------------------------------|
| Oil Leak: Swing Device | None | Oil Leak: Pump Device | None                            |
| Overall Rating         |      |                       |                                 |
| Appearance Evaluation  | Fair | Rust / Corrosion      | Moderate / within Service Limit |
| Overall Rating         | Fair |                       |                                 |