

1987 Tadano TR-200M-3-00103 Truck Crane/Rough Terrain Crane

Basic information			
Model	TR-200M-3-00103	Serial No.	520996
Product category	Truck Crane/Rough Terrain Crane	Manufacturer	Tadano
Year of manufacture	1987	Working hours	
Engine No.			
Detail Information			
Other	Air Conditioner		
Appearance			
Main Frame	Rusted / Corroded	Track Frame	Rusted / Corroded
Cabin / Driving seat	Rusted / Corroded, Glass: Broken	Door	Stiff Hinges, Not Closed Properly, Latch Malfunction
Interior			
Seat	Torn	Console	Faded, Malfunction
Air Conditioner	Malfunction		
Oil / Water / Air Leakage			
Main boom	Repair Mark	Jib boom	Normal
Wear: Front Pins & Bushings	Moderate / within Service Limit	Wear: Other Pins	Moderate / within Service Limit
Sieve	Moderate / within Service Limit	Wire rope	Required to Repair, Heavy / Required to replace
Engine	Normal	Exhaust Gas Color	White Smoke
Traveling	Normal	Swing	Swing brake: not works properly
Wear: Swing Bearing	Excessive / Required to Repair	Transmission / Torque Converter	Normal
Hoisting device	Normal	Break	Poor Operation
Side Break	Poor Operation	Outrigger	Normal
Safety device	Malfunction	Pump Device	Abnormal Noise, Required to Repair
Operation			
Scratches: Tire (Front-Right Wheel)	Moderate / within Service Limit	Scratches: Tire (Rear-Right Wheel)	Moderate / within Service Limit
Scratches: Tire (Front-Left Wheel)	Moderate / within Service Limit	Scratches: Tire (Rear-Left Wheel)	Moderate / within Service Limit
Wear: Tire (Front-Right wheel)	Excessive / Required to replace	Wear: Tire (Front-Left Wheel)	Excessive / Required to replace
Wear: Tire (Rear-Right Wheel)	Excessive / Required to replace	Wear: Tire (Rear-Left Wheel)	Excessive / Required to replace
Oil Leak: Axle	Slight Film	Oil Leak: Travel Device	Slight Film
Oil Leak: Travel Pipes	Slight Film	Oil Leak: Front Pipes	No
Undercarriage / Chassis / Tires			
Oil Leak: Boom Cylinder	Moderate Oozing	Telescopic cylinder	No
Oil Leak: Outrigger cylinder	No	Oil Leak: Engine	Slight Film
Compressor	Normal	Oil Leak: Pilot Pipes	No
Oil Leak: Pilot Valve	No	Oil Leak: Center Joint	Slight Film
Oil Leak: Swing Device	Slight Film	Hoisting device	Slight Film
Pump Device	Moderate Oozing	Transmission / Torque Converter	Slight Film
Front & Pins			
Oil Leak: Oil Cooler	No	Leak: Radiator	No
Leak: Cooling Pipes	No	Oil Leak: Fuel System	No
Oil Leak: Control Valve	Slight Film		

Overall Rating			
Appearance Evaluation	Poor	Rust / Corrosion	Heavy
Overall Rating	for Parts Cannibalization		