

1900 Hitachi CG110-2-SC Carrier

Basic information			
Model	CG110-2-SC	Serial No.	10248
Product category	Carrier	Manufacturer	Hitachi
Year of manufacture	1900	Working hours	
Engine No.			
Detail Information			
Type of Shoe	Rubber	Loading platform type	Gravel carrier
Other	Air Conditioner	Main Frame	Good Condition
Appearance			
Track Frame	Good Condition	Front bumper	Deformed / Dent
Cabin / Canopy	Rusted / Corroded	Door	Good Condition
Cabin Interior	Torn		
Interior			
Seat	Good Condition	Console	Good Condition
Air Conditioner	Good Condition		
Undercarriage / Chassis / Tires			
Wear: Rubber Shoe	Moderate / within Service Limit	Wear: Pivot shaft	No
Broken / Missing: Rollers	1 - 4 Pieces	Wear: Front Idler (Right)	Moderate / within Service Limit
Wear: Front Idler (Left)	Moderate / within Service Limit	Wear: Sprocket (Right)	Moderate / within Service Limit
Wear: Sprocket (Left)	Moderate / within Service Limit	Oil Leak: Travel Device	No
Oil Leak: Travel Pipes	No	Oil Leak: Oil Cooler	No
Leak: Radiator	No	Leak: Cooling Pipes	No
Oil Leak: Fuel System	No	Oil Leak: Control Valve	No
Oil Leak: Low Pressure Pipes	No		
Operation			
Broken / Crack: Rubber Shoe (Right)	Excessive / Required to replace	Broken / Crack: Rubber Shoe (Left)	Moderate / within Service Limit, Excessive / Required to replace
Missing: Rubber Shoe Core	No	Wear: Upper Rollers	Moderate / within Service Limit
Wear: Lower Rollers	Moderate / within Service Limit	Oil Leak: Rollers	1 - 4 Pieces
Oil / Water / Air Leakage			
Oil Leak: High Pressure Pipes	No	Pump Device	No
Oil Leak: Pilot Pipes	No	Engine	Normal
Exhaust Gas Color	Normal	Traveling	Normal
Dump cylinder (Right)	No	Break	Normal
Dump cylinder (Left)	No	Side Break	Normal
Oil Leak: Engine	No	Dumping	Normal
Other working device	Normal		
?? ? ??			
Vessel	Deformation: Moderate, Cracked	Frame	Normal
Overall Rating			
Appearance Evaluation	Fair	Rust / Corrosion	Moderate / within Service Limit
Overall Rating	Fair		