

1900 Yanmar C80R-2 Carrier

Basic information			
Model	C80R-2	Serial No.	20560C
Product category	Carrier	Manufacturer	Yanmar
Year of manufacture	1900	Working hours	
Engine No.			
Detail Information			
Type of Shoe	Rubber	Loading platform type	Gravel carrier
Main Frame	Good Condition		
Appearance			
Track Frame	Good Condition	Front bumper	Deformed / Dent
Cabin / Canopy	Good Condition		
Interior			
Seat	Good Condition	Console	Good Condition
Operation			
Wear: Track Link Tread (Left)	Moderate / within Service Limit	Broken / Crack: Rubber Shoe (Right)	Moderate / within Service Limit
Broken / Crack: Rubber Shoe (Left)	Moderate / within Service Limit	Missing: Rubber Shoe Core	No
Wear: Upper Rollers	Moderate / within Service Limit	Wear: Lower Rollers	Moderate / within Service Limit
Oil Leak: Rollers	1 - 4 Pieces		
Undercarriage / Chassis / Tires			
Wear: Rubber Shoe	Moderate / within Service Limit	Wear: Pivot shaft	3 - 4 Pieces
Broken / Missing: Rollers	No	Wear: Front Idler (Right)	Moderate / within Service Limit
Wear: Front Idler (Left)	Moderate / within Service Limit	Wear: Sprocket (Right)	Moderate / within Service Limit
Wear: Sprocket (Left)	Moderate / within Service Limit	Oil Leak: Travel Device	No
Oil Leak: Travel Pipes	No	Oil Leak: Oil Cooler	No
Leak: Radiator	No	Leak: Cooling Pipes	No
Oil Leak: Fuel System	Slight Film	Oil Leak: Control Valve	No
Oil Leak: Low Pressure Pipes	No		
Oil / Water / Air Leakage			
Oil Leak: High Pressure Pipes	No	Pump Device	No
Oil Leak: Pilot Pipes	No	Engine	Normal
Exhaust Gas Color	Normal	Traveling	Normal
Dump cylinder (Right)	No	Break	Normal
Side Break	Normal	Oil Leak: Engine	No
Dumping	Normal	Other working device	Normal
?? ? ??			
Vessel	Deformation: Moderate, Cracked	Frame	Normal
Overall Rating			
Appearance Evaluation	Fair	Rust / Corrosion	Moderate / within Service Limit
Overall Rating	Fair		