

2003 Hitachi EG70R Carrier

Basic information			
Model	EG70R	Serial No.	10244
Product category	Carrier	Manufacturer	Hitachi
Year of manufacture	2003	Working hours	
Engine No.			
Detail Information			
Type of Shoe	Rubber	Loading platform type	Swivel
Other	Air Conditioner	Main Frame	Good Condition
Appearance			
Track Frame	Good Condition	Front bumper	Good Condition
Cabin / Canopy	Good Condition	Door	Good Condition
Cabin Interior	Good Condition		
Interior			
Seat	Dirty	Console	Good Condition
Air Conditioner	Good Condition	Wear: Track Link Stretching (Right)	Moderate
Undercarriage / Chassis / Tires			
Fixation: Track shoe	No	Wear: Rubber Shoe	Moderate / within Service Limit
Wear: Pivot shaft	No	Broken / Missing: Rollers	No
Wear: Front Idler (Right)	Moderate / within Service Limit	Wear: Front Idler (Left)	Moderate / within Service Limit
Wear: Sprocket (Right)	Moderate / within Service Limit	Wear: Sprocket (Left)	Moderate / within Service Limit
Oil Leak: Travel Device	No	Oil Leak: Travel Pipes	No
Oil Leak: Oil Cooler	No	Leak: Radiator	No
Leak: Cooling Pipes	No	Oil Leak: Fuel System	No
Oil Leak: Control Valve	No	Oil Leak: Low Pressure Pipes	No
Operation			
Wear: Track Link Stretching (Left)	Moderate	Wear: Track Link Tread (Right)	Moderate / within Service Limit
Wear: Track Link Tread (Left)	Moderate / within Service Limit	Broken / Crack: Rubber Shoe (Right)	Moderate / within Service Limit
Broken / Crack: Rubber Shoe (Left)	Moderate / within Service Limit	Missing: Rubber Shoe Core	No
Wear: Upper Rollers	Moderate / within Service Limit	Wear: Lower Rollers	Moderate / within Service Limit
Oil Leak: Rollers	No		
Oil / Water / Air Leakage			
Oil Leak: High Pressure Pipes	No	Oil Leak: Center Joint	No
Oil Leak: Swing Device	No	Pump Device	No
Oil Leak: Pilot Valve	No	Oil Leak: Pilot Pipes	No
Engine	Normal	Exhaust Gas Color	Normal
Swing	Normal	Wear: Swing Bearing	Slight
Traveling	Normal	Dump cylinder (Right)	No
Break	Poor Operation	Dump cylinder (Left)	No
Oil Leak: Engine	No	Dumping	Normal
?? ? ??			
Vessel	Deformation: Moderate	Frame	Normal
Overall Rating			
Appearance Evaluation	Fair	Rust / Corrosion	Moderate / within Service Limit
Overall Rating	Fair		

